

# Table of Contents

---

Mapping.....	2-8
Floor Plan.....	9-10
Tax Records & Title Report.....	11-30
Well Information.....	31-35
Septic Information.....	36-100
Seller's Property Disclosures.....	101-111
Inspection Report.....	112-142


Chris Martin - Alex Larson - Ashley Lacer - Shannon Forrest  
541.660.5111  
[Team@MOPG.com](mailto:Team@MOPG.com)



# Mapping



 Boundary



 Boundary



 Boundary

Boundary 1.02 ac

SOIL CODE	SOIL DESCRIPTION	ACRES	%	CPI	NCCPI	CAP
6B	Agate-Winlo complex, 0 to 5 percent slopes	0.78	76.47	0	35	4s
150E	Provig very gravelly loam, 15 to 35 percent slopes	0.24	23.53	0	43	6e
TOTALS		1.02(*)	100%	-	36.88	4.47

(\*) Total acres may differ in the second decimal compared to the sum of each acreage soil. This is due to a round error because we only show the acres of each soil with two decimal.

### Capability Legend

Increased Limitations and Hazards  
Decreased Adaptability and Freedom of Choice Users

Land, Capability

	1	2	3	4	5	6	7	8
'Wild Life'	•	•	•	•	•	•	•	•
Forestry	•	•	•	•	•	•	•	
Limited	•	•	•	•	•	•	•	
Moderate	•	•	•	•	•	•		
Intense	•	•	•	•	•			
Limited	•	•	•	•				
Moderate	•	•	•					
Intense	•	•						
Very Intense	•							

**Grazing Cultivation**

(c) climatic limitations (e) susceptibility to erosion  
(s) soil limitations within the rooting zone (w) excess of water


130 Kitty Drive  
Oregon, AC +/-



 Boundary


# 130 Kitty Drive

Oregon, AC +/-



 Boundary

# Floor Plan



GROSS INTERNAL AREA  
 TOTAL: 1,103 sq.ft  
 FLOOR 1: 1,103 sq.ft

SIZE AND DIMENSIONS ARE APPROXIMATE, ACTUAL MAY VARY

# Tax Records & Title Report



**First American Title™**

First American Title Insurance Company

1225 Crater Lake Avenue, Suite 101  
Medford, OR 97504  
Phn - (541)779-7250  
Fax - (866)400-2250

Order No.: 7161-4383859  
May 22, 2026

**FOR QUESTIONS REGARDING YOUR CLOSING, PLEASE CONTACT:**

LISA TATE, Escrow Officer/Closer  
Phone: (541)779-7250x5435 - Fax: (866)839-7125- Email:LTate@firstam.com  
First American Title Insurance Company  
1225 Crater Lake Avenue, Suite 101, Medford, OR 97504

**FOR ALL QUESTIONS REGARDING THIS PRELIMINARY REPORT, PLEASE CONTACT:**

**Mark Fliegel**, Title Officer  
Phone: (541)779-7250 - Email: mfliegel@firstam.com

**Preliminary Title Report**

This report is for the exclusive use of the parties herein shown and is preliminary to the issuance of a title insurance policy and shall become void unless a policy is issued, and the full premium paid.

Please be advised that any provision contained in this document, or in a document that is attached, linked or referenced in this document, that under applicable law illegally discriminates against a class of individuals based upon personal characteristics such as race, color, religion, sex, sexual orientation, gender identity, familial status, disability, national origin, or any other legally protected class, is illegal and unenforceable by law.

Situs Address as disclosed on Jackson County Tax Roll:

130 Kitty Drive, Eagle Point, OR 97524

2021 ALTA Owners Standard Coverage	Liability \$	539,500.00	Premium \$	1,410.00
2021 ALTA Owners Extended Coverage	Liability \$		Premium \$	
2021 ALTA Lenders Standard Coverage	Liability \$		Premium \$	
2021 ALTA Lenders Extended Coverage	Liability \$	TBD	Premium \$	TBD
Endorsement 9.10, 22 & 8.1			Premium \$	100.00
Govt Service Charge			Cost \$	
Other			Cost \$	

**Proposed Insured Lender: Lender To Be Determined**

**Proposed Borrower: TBD**

We are prepared to issue Title Insurance Policy or Policies of First American Title Insurance Company, a Nebraska Corporation in the form and amount shown above, insuring title to the following described land:

The land referred to in this report is described in Exhibit A attached hereto.

and as of May 18, 2026 at 8:00 a.m., [title to the fee simple estate is vested in:](#)

Linda K. Pickthorne

Subject to the exceptions, exclusions, and stipulations which are ordinarily part of such Policy form and the following:

1. Taxes or assessments which are not shown as existing liens by the records of any taxing authority that levies taxes or assessments on real property or by the public records; proceedings by a public agency which may result in taxes or assessments, or notices of such proceedings, whether or not shown by the records of such agency or by the public records.
2. Facts, rights, interests or claims which are not shown by the public records but which could be ascertained by an inspection of the land or by making inquiry of persons in possession thereof.
3. Easements, or claims of easement, not shown by the public records; reservations or exceptions in patents or in Acts authorizing the issuance thereof; water rights, claims or title to water.
4. Any encroachment (of existing improvements located on the subject land onto adjoining land or of existing improvements located on adjoining land onto the subject land), encumbrance, violation, variation, or adverse circumstance affecting the title that would be disclosed by an accurate and complete land survey of the subject land.
5. Any lien, or right to a lien, for services, labor, material, equipment rental or workers compensation heretofore or hereafter furnished, imposed by law and not shown by the public records.

**The exceptions to coverage 1-5 inclusive as set forth above will remain on any subsequently issued Standard Coverage Title Insurance Policy.**

**In order to remove these exceptions to coverage in the issuance of an Extended Coverage Policy the following items are required to be furnished to the Company; additional exceptions to coverage may be added upon review of such information:**

- A. Survey or alternative acceptable to the company
  - B. Affidavit regarding possession
  - C. Proof that there is no new construction or remodeling of any improvement located on the premises. In the event of new construction or remodeling the following is required:
    - i. Satisfactory evidence that no construction liens will be filed; or
    - ii. Adequate security to protect against actual or potential construction liens;
    - iii. Payment of additional premiums as required by the Industry Rate Filing approved by the Insurance Division of the State of Oregon
6. Water rights, claims or title to water, whether or not shown by the public record.
  7. Any claim to (a) ownership of or rights to minerals and similar substances, including but not limited to ores, metals, coal, lignite, oil, gas, uranium, clay, rock, sand, and gravel located in, on, or under the Land or produced from the Land, whether such ownership or rights arise by lease, grant, exception, conveyance, reservation, or otherwise; and (b) any rights, privileges, immunities, rights of way, and easements associated therewith or appurtenant thereto, whether or not the interests or rights excepted in (a) or (b) appear in the Public Records.
  8. These premises are situated in the Sams Valley Irrigation District, notice which appears in instrument recorded May 29, 1980 as Document No. [80-10053](#), Official Records of Jackson County, Oregon, and subject to the levies and assessments thereof, water and irrigation rights, easements for ditches and canals and regulations concerning the same.

9. Easement for electric transmission and distribution lines of one or more wires, and all necessary or desirable appurtenances, including telephone and telegraph wires, towers, poles, props, guys and other supports; and related matters.  
 Recorded: July 06, 1949  
 Recording Information: [Volume 320, Page 57](#)  
 Grantee: Pacific Power & Light Company  
 Affects: (Specific Location Not Given)
10. Deed of Trust and the terms and conditions thereof.  
 Grantor/Trustor: Linda Pickthorne  
 Grantee/Beneficiary: Mortgage Electronic Registration Systems, Inc., MERS solely as a nominee for Guild Mortgage Company LLC, a California limited liability company, its successors and assigns  
 Trustee: Clear Recon Corp.  
 Amount: \$425,000.00  
 Recorded: August 25, 2022  
 Recording Information: Document No. [2022-026175](#)
11. Restrictive Covenants, including the terms and provisions thereof, as imposed by Jackson County Department of Planning and Development, through the Jackson County Land Development Ordinance, and recorded February 07, 2023 as Document No. [2023-002389](#), Official Records of Jackson County, Oregon.
12. Restrictive Covenants, including the terms and provisions thereof, as imposed by Jackson County Department of Planning and Development, through the Jackson County Land Development Ordinance, and recorded February 21, 2023 as Document No. [2023-003240](#), Official Records of Jackson County, Oregon.
13. Restrictive Covenants, including the terms and provisions thereof, as imposed by Jackson County Department of Planning and Development, through the Jackson County Land Development Ordinance, and recorded August 30, 2023 as Document No. [2023-018389](#), Official Records of Jackson County, Oregon.
14. **This transaction may be subject to the FinCEN Residential Real Estate Reporting Rule ("RRE Rule") issued pursuant to the Bank Secrecy Act, effective March 1, 2026. Information necessary to comply with the RRE Rule must be obtained and provided to the Reporting Person, as defined in the RRE Rule, prior to closing.**

- END OF EXCEPTIONS -

NOTE: We find no matters of public record against TBD that will take priority over any trust deed, mortgage or other security instrument given to purchase the subject real property as established by ORS 18.165.

NOTE: We find no judgments or United States Internal Revenue liens against Linda K. Perdue

NOTE: Taxes for the year 2025-2026 PAID IN FULL

Tax Amount: \$1,763.07  
 Map No.: 341W20A 4700  
 Property ID: [1-022323-1](#)  
 Tax Code No.: 9-06

NOTE: An application to Exempt Mobile Home from Registration and Titling was recorded October 17, 1994 as Document No. [94-37096](#) of Jackson County Official Records.

NOTE: According to the public records, there has been no conveyance of the land within a period of 24 months prior to the date of this report, except as follows:

None

**THANK YOU FOR CHOOSING FIRST AMERICAN TITLE!  
WE KNOW YOU HAVE A CHOICE!**

**MARK FLIEGEL**  
TITLE OFFICER  
mfliegel@firstam.com

**Recording Information**

For county recording requirements and fees visit

<https://jacksoncountyor.gov/departments/clerk/recording/index.php>

**NOTE:** Non-standard Document Fee of \$20.00, if applicable, will be imposed by the county clerk for documents presented for recording that fail to meet the requirements established by ORS 205.27

You can also calculate fees by using our Title Fee Calculator at <https://facc.firstam.com/>.

cc: Lender To Be Determined

cc: Chris Martin, John L. Scott Real Estate  
871 Medford Center, Medford, OR 97504

**Exhibit "A"**

Real property in the County of Jackson, State of Oregon, described as follows:

Lot 1 in Block 1 of LONG BRANCH SUBDIVISION, in Jackson County, Oregon, according to the Official Plat thereof, recorded in [Volume 11, Page 30](#) of plat records.



## First American Title Insurance Company

### SCHEDULE OF EXCLUSIONS FROM COVERAGE

#### ALTA LOAN POLICY (07/01/21)

The following matters are excluded from the coverage of this policy, and the Company will not pay loss or damage, costs, attorneys' fees, or expenses that arise by reason of:

1. a. any law, ordinance, permit, or governmental regulation (including those relating to building and zoning) that restricts, regulates, prohibits, or relates to:
  - i. the occupancy, use, or enjoyment of the Land;
  - ii. the character, dimensions, or location of any improvement erected on the Land;
  - iii. the subdivision of land; or
  - iv. environmental remediation or protection.
- b. any governmental forfeiture, police, regulatory, or national security power.
- c. the effect of a violation or enforcement of any matter excluded under Exclusion 1.a. or 1.b.  
Exclusion 1 does not modify or limit the coverage provided under Covered Risk 5 or 6.
2. Any power of eminent domain. Exclusion 2 does not modify or limit the coverage provided under Covered Risk 7.
3. Any defect, lien, encumbrance, adverse claim, or other matter:
  - a. created, suffered, assumed, or agreed to by the Insured Claimant;
  - b. not Known to the Company, not recorded in the Public Records at the Date of Policy, but Known to the Insured Claimant and not disclosed in writing to the Company by the Insured Claimant prior to the date the Insured Claimant became an Insured under this policy;
  - c. resulting in no loss or damage to the Insured Claimant;
  - d. attaching or created subsequent to the Date of Policy (Exclusion 3.d. does not modify or limit the coverage provided under Covered Risk 11, 13, or 14); or
  - e. resulting in loss or damage that would not have been sustained if consideration sufficient to qualify the Insured named in Schedule A as a bona fide purchaser or encumbrancer had been given for the Insured Mortgage at the Date of Policy.
4. Unenforceability of the lien of the Insured Mortgage because of the inability or failure of an Insured to comply with applicable doing-business law.
5. Invalidity or unenforceability of the lien of the Insured Mortgage that arises out of the transaction evidenced by the Insured Mortgage and is based upon usury law or Consumer Protection Law.
6. Any claim, by reason of the operation of federal bankruptcy, state insolvency, or similar creditors' rights law, that the transaction creating the lien of the Insured Mortgage is a:
  - a. fraudulent conveyance or fraudulent transfer;
  - b. voidable transfer under the Uniform Voidable Transactions Act; or
  - c. preferential transfer:
    - i. to the extent the Insured Mortgage is not a transfer made as a contemporaneous exchange for new value; or
    - ii. for any other reason not stated in Covered Risk 13.b.
7. Any claim of a PACA-PSA Trust. Exclusion 7 does not modify or limit the coverage provided under Covered Risk 8.
8. Any lien on the Title for real estate taxes or assessments imposed by a governmental authority and created or attaching between the Date of Policy and the date of recording of the Insured Mortgage in the Public Records. Exclusion 8 does not modify or limit the coverage provided under Covered Risk 2.b. or 11.b.
9. Any discrepancy in the quantity of the area, square footage, or acreage of the Land or of any improvement to the Land.

#### ALTA OWNER'S POLICY (07/01/21)

The following matters are excluded from the coverage of this policy, and the Company will not pay loss or damage, costs, attorneys' fees, or expenses that arise by reason of:

1. a. any law, ordinance, permit, or governmental regulation (including those relating to building and zoning) that restricts, regulates, prohibits, or relates to:
  - i. the occupancy, use, or enjoyment of the Land;
  - ii. the character, dimensions, or location of any improvement on the Land;
  - iii. the subdivision of land; or
  - iv. environmental remediation or protection.
- b. any governmental forfeiture, police, regulatory, or national security power.
- c. the effect of a violation or enforcement of any matter excluded under Exclusion 1.a. or 1.b.  
Exclusion 1 does not modify or limit the coverage provided under Covered Risk 5 or 6.
2. Any power of eminent domain. Exclusion 2 does not modify or limit the coverage provided under Covered Risk 7.
3. Any defect, lien, encumbrance, adverse claim, or other matter:
  - a. created, suffered, assumed, or agreed to by the Insured Claimant;
  - b. not Known to the Company, not recorded in the Public Records at the Date of Policy, but Known to the Insured Claimant and not disclosed in writing to the Company by the Insured Claimant prior to the date the Insured Claimant became an Insured under this policy;
  - c. resulting in no loss or damage to the Insured Claimant;
  - d. attaching or created subsequent to the Date of Policy (Exclusion 3.d. does not modify or limit the coverage provided under Covered Risk 9 or 10); or
  - e. resulting in loss or damage that would not have been sustained if consideration sufficient to qualify the Insured named in Schedule A as a bona fide purchaser had been given for the Title at the Date of Policy.
4. Any claim, by reason of the operation of federal bankruptcy, state insolvency, or similar creditors' rights law, that the transaction vesting the Title as shown in Schedule A is a:
  - a. fraudulent conveyance or fraudulent transfer;
  - b. voidable transfer under the Uniform Voidable Transactions Act; or
  - c. preferential transfer:
    - i. to the extent the instrument of transfer vesting the Title as shown in Schedule A is not a transfer made as a contemporaneous exchange for new value; or
    - ii. for any other reason not stated in Covered Risk 9.b.
5. Any claim of a PACA-PSA Trust. Exclusion 5 does not modify or limit the coverage provided under Covered Risk 8.
6. Any lien on the Title for real estate taxes or assessments imposed or collected by a governmental authority that becomes due and payable after the Date of Policy. Exclusion 6 does not modify or limit the coverage provided under Covered Risk 2.b.
7. Any discrepancy in the quantity of the area, square footage, or acreage of the Land or of any improvement to the Land.

**SCHEDULE OF STANDARD EXCEPTIONS**

1. Taxes or assessments which are not shown as existing liens by the records of any taxing authority that levies taxes or assessments on real property or by the public records; proceedings by a public agency which may result in taxes or assessments, or notices of such proceedings, whether or not shown by the records of such agency or by the public records.
2. Facts, rights, interests or claims which are not shown by the public records but which could be ascertained by an inspection of the land or by making inquiry of persons in possession thereof.
3. Easements, or claims of easement, not shown by the public records; reservations or exceptions in patents or in Acts authorizing the issuance thereof; water rights, claims or title to water.
4. Any encroachment (of existing improvements located on the subject land onto adjoining land or of existing improvements located on adjoining land onto the subject land), encumbrance, violation, variation, or adverse circumstance affecting the title that would be disclosed by an accurate and complete land survey of the subject land.
5. Any lien" or right to a lien, for services, labor, material, equipment rental or workers compensation heretofore or hereafter furnished, imposed by law and not shown by the public records.

---

NOTE: A SPECIMEN COPY OF THE POLICY FORM (OR FORMS) WILL BE FURNISHED UPON REQUEST

Rev. 07-01-21



## Privacy Notice

**Last Updated and Effective Date:** December 1, 2025

First American Financial Corporation and its subsidiaries and affiliates (collectively, "First American," "we," "us," or "our") describe in our full privacy notice ("Notice"), which can be found at <https://www.firstam.com/privacy-policy/>, how we collect, use, store, sell or share your personal information when: (1) you access or use our websites, mobile applications, web-based applications, or other digital platforms where the Notice is posted ("Sites"); (2) you use our products and services ("Services"); (3) you communicate with us in any manner, including by e-mail, in-person, telephone, or other communication method ("Communications"); (4) we obtain your information from third parties, including service providers, business partners, and governmental departments and agencies ("Third Parties"); and (5) you interact with us to conduct business dealings, such as the personal information we obtain from business partners and service providers and contractors who provide us certain business services ("B2B"). This shortened form of the Notice describes some of the terms contained in the full Privacy Notice. Personal information is sometimes also referred to as personal data, personally identifiable information or other like terms to mean any information that directly or indirectly identifies you or is reasonably capable of being associated with you or your household. However, certain types of information are not personal information and thus, not within the scope of our Notice, such as: (1) publicly available information; and (2) de-identified and aggregated data that is not capable of identifying you. If we use de-identified or aggregated data, we commit to maintain and use the information in a non-identifiable form and not attempt to reidentify the information, unless required or permitted by law.

This Notice applies wherever it is posted. To the extent a First American subsidiary or affiliate has different privacy practices, such entity shall have their own privacy statement posted as applicable.

Please note that this Notice does **not** apply to any information we collect from job candidates and employees. Our employee and job candidate privacy notice can be found [here](#).

**What Type Of Personal Information Do We Collect About You?** We collect a variety of categories of personal information about you. To learn more about the categories of personal information we collect, please visit <https://www.firstam.com/privacy-policy/>.

**How Do We Collect Your Personal Information?** We collect your personal information: (1) directly from you; (2) automatically when you interact with us; and (3) from other parties, including business parties and affiliates.

**How Do We Use Your Personal Information?** We may use your personal information in a variety of ways, including but not limited to providing the services you have requested, fulfilling your transactions, complying with relevant laws and our policies, and handling a claim. To learn more about how we may use your personal information, please visit <https://www.firstam.com/privacy-policy/>.

**How Do We Disclose Your Personal Information?** We may disclose your personal information, including to subsidiaries, affiliates, and to unaffiliated parties, such as service providers and contractors: (1) with your consent; (2) in a business transfer; and (3) for legal process and protection. Although we do not "sell" your information in the traditional sense, the definition of "sale" is broad under the CCPA that some disclosures of your information to third parties may be considered a "sale" or "sharing" for targeted advertising. To learn more about how we disclose your personal information, please visit <https://www.firstam.com/privacy-policy/>.

**How Do We Store and Protect Your Personal Information?** The security of your personal information is important to us. We take all commercially reasonable steps to make sure your personal information is protected. We use our best efforts to maintain commercially reasonable technical, organizational, and physical safeguards, consistent with applicable law, to protect your personal information.

**How Long Do We Keep Your Personal Information?** We keep your personal information for as long as necessary in accordance with the purpose for which it was collected, our business needs, and our legal and regulatory obligations.



**Your Choices** We provide you the ability to exercise certain controls and choices regarding our collection, use, storage, and disclosure of your personal information. You can learn more about your choices by visiting <https://www.firstam.com/privacy-policy/>.

**International Jurisdictions:** Our Services are offered in the United States of America (US), and are subject to US federal, state, and local law. If you are accessing the Services from another country, please be advised that you may be transferring your information to us in the US, and you consent to that transfer and use of your information in accordance with the Notice. You also agree to abide by the applicable laws of applicable US federal, state, and local laws concerning your use of the Services, and your agreements with us.

**Changes to Our Notice:** We may change the Notice from time to time. Any and all changes to the Notice will be reflected on this page and in the full Notice, and where appropriate provided in person or by another electronic method.

**YOUR CONTINUED USE, ACCESS, OR INTERACTION WITH OUR SERVICES OR YOUR CONTINUED COMMUNICATIONS WITH US AFTER THIS NOTICE HAS BEEN PROVIDED TO YOU WILL REPRESENT THAT YOU HAVE READ AND UNDERSTOOD THE NOTICE.**

**For California Residents** If you are a California resident, you may have certain rights under California law, including but not limited to the California Consumer Privacy Act of 2018, as amended by the California Privacy Rights Act and its implementing regulations. To learn more, please visit <https://www.firstam.com/privacy-policy/>.

**Contact Us:** [dataprivacy@firstam.com](mailto:dataprivacy@firstam.com) or toll free at 1-866-718-0097.


787.00 (M) 899.88 (CALC)

TOWNSHIP 34 RANGE 1W SECTION 20A

THIS MAP IS FOR LOCATION PURPOSES ONLY  
 NO LIABILITY IS ASSUMED FOR VARIATIONS  
 DISCLOSED BY SURVEY OR COUNTY RECORDS

FIRST AMERICAN TITLE

N ↑



SEE MAP 34 1W 20

[Account Sequence](#)   
 [Map TL Sequence](#)   
 Assessment Year 2026 ▼   
 [Print Window](#)   
 [Close Window](#)

**Assessment Info for Account 1-022323-1 Map 341W20A Taxlot 4700**  
 Report For Assessment Purposes Only Created March 26, 2026

Account Info		Tax Year 2025 Info		Land Info	
Account	1-022323-1	<a href="#">Pay Taxes Online</a>		Tax Code	9-06
Map Taxlot	341W20A 4700	Tax Report	<a href="#">Details</a>	Acreage	1.02
Owner	PERDUE LINDA K	TAX Statement	<a href="#">Details</a>	<a href="#">Zoning</a>	
<a href="#">Situs Address</a>	130 KITTY DR EAGLE POINT/COUNTY R	Tax History	<a href="#">Details</a>	<a href="#">Land Class</a>	
Mailing Address	PERDUE LINDA K 130 KITTY DR EAGLE POINT OR, 97524-9759	Tax Details	<a href="#">Details</a>	RR-5	
<a href="#">Associated Taxlots</a> 1 Acct		Tax Rates	<a href="#">Details</a>	HS 0.00 Ac RT 1.02 Ac	
9-06 MS	<a href="#">3-011598-6</a> <a href="#">341W20A 4700</a> ACTIVE			<a href="#">Property Class</a>	409
Appraiser				Unit ID	117871-1
				Maintenance Area	1
				Neighborhood	402
				Study Area	40
				Account Status	ACTIVE
				Tax Status	Assessable
				Sub Type	NORMAL
				<a href="#">MS Park ID</a>	

**Sales Data (ORCATS)**

Last Sale (consideration > 0)	Sale Date	Instrument Number	Sales History
\$ 0	Sep 27, 2024	<a href="#">2025-551</a>	<a href="#">Details</a>
<input checked="" type="checkbox"/> <b>Value Summary Detail ( For Assessment Year 2025 )</b> (2026 values are unavailable)			
<input type="checkbox"/> <b>Market Value Summary ( For Assessment Year 2025 )</b> (2026 values are unavailable)			

Code Area	Type	Acreage	RMV	M5	MAV	AV
9-06	LAND	1.02	\$ 136,930	\$ 136,930		
9-06	IMPR	0,00	\$ 90,690	\$ 90,690		
PSO Value History <a href="#">Details</a>			Total:	\$ 227,620	\$ 173,540	\$ 173,540

**Improvements**

Building #	Code Area	Year Built	Eff Year Built	Stat Class	Description	Type	SqFt	% Complete	
1	9-06	1900	1900	<a href="#">300</a>	Residential Other Improvements	RESIDENCE	0	100 %	<a href="#">Details</a>
2	9-06	1987	1987	<a href="#">952</a>	Double wide	MANF STRCT	1152	100 %	<a href="#">Details</a>

**Photos and Scanned Documents**

Type	Files	
ACCOUNT PHOTO	3	<a href="#">PDF</a>
SCANNED ASSESSOR DOCUMENTS	(See new portal)	<a href="#">Portal</a>

**Improvement Comments**

**Account Comments**

(1) 3-11598-6 (2) EM 8247>>>9/20/05 REMOVED BS. 1.02 ACRE IN RR-5 ZONING #136>>> 6/22/10 ADDED LS #145 >>> 2025-03-05 Updated MA-SA-NH>>>.

**Exemptions / Special Assessments / Notations / Potential Liability**

Real Property Special Assessments				
Tax Year Applied	Code	Description	Amount	Acres
2026	40	FIRE PATROL TIMBER	\$20,00	1.02
2026	39	FIRE IMPROVEMENT SURCHARGE	\$58,00	0,00

Notations			
Description	Tax Amount	Year Added	Value Amount
STATE FIRE PROTECTION		2009	
OTHER ERRORS 311,205(1)(b)(C) - DECREASE		2012	

**Location Map**



County of Jackson, OR, Bureau of Land Management, State of Oregon, State of Oregon DOT, State of Oregon GEO, Esri Canada, Esri, HERE, Garmin, I... Powered by Esri

[Close Window](#)   
 [Print Window](#)

# Improvement Summary

*JACKSON County*

**For Assessment Year 2026**

<b>Account ID</b>	10223231	
<b>Map</b>	341W20-A0-04700	<b>Situs</b> 130 KITTY DR EAGLE POINT/COUNTY OR
<b>Mailing</b>	PERDUE LINDA K 130 KITTY DR EAGLE POINT OR 97524-9759	

Bldg	Code Area	Stat Class	Year Built	Comp %	Description	Sqft
2	0906	952	1987	100	952 - Double wide	1,152

Rooms:

### Floors

Description	Class	Comp %	OR %	Sqft
First Floor	5	100		1152

### Improvement Inventory

Description	Qty/Size	Description	Qty/Size
MS BATH: FULL	2	MS ROOF: COMP	1152
MS HEARTH: AVERAGE	1	MS SIDING: WOOD	1152
MS SKIRTING: AVERAGE	1		

### Accessories

Description	Size	Qty
MS AWNING: 3 AVERAGE	360	0
MS AWNING: 3 AVERAGE	360	0
CONCRETE	360	

**Total RMV** \$74,010



**STATEMENT OF TAX ACCOUNT**  
**JACKSON COUNTY TAX COLLECTOR**  
**JACKSON COUNTY COURTHOUSE**  
**MEDFORD, OR 97501**  
(541) 774-6541

26-Mar-2026

PERDUE LINDA K  
130 KITTY DR  
EAGLE POINT OR 97524-9759

Tax Account #	10223231	Lender Name	CLG - Guild Mortgage Company
Account Status	A	Loan Number	
Roll Type	Real	Property ID	0906
Situs Address	130 KITTY DR EAGLE POINT/COUNTY OR	Interest To	Mar 26, 2026

**Tax Summary**

Tax Year	Tax Type	Total Due	Current Due	Interest Due	Discount Available	Original Due	Due Date
2025	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,763.07	Nov 15, 2025
2024	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,713.64	Nov 15, 2024
2023	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,656.08	Nov 15, 2023
2022	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,613.37	Nov 15, 2022
2021	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,835.72	Nov 15, 2021
2020	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,982.12	Nov 15, 2020
2019	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,614.13	Nov 15, 2019
2018	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,578.38	Nov 15, 2018
2017	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,541.50	Nov 15, 2017
2016	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,395.11	Nov 15, 2016
2015	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,348.20	Nov 15, 2015
2014	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,310.30	Nov 15, 2014
2013	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,221.92	Nov 15, 2013
2012	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,183.15	Nov 15, 2012
2011	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,149.21	Nov 15, 2011
2010	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,377.83	Nov 15, 2010
2009	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,340.94	Nov 15, 2009
2008	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,355.32	Nov 15, 2008
2007	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,305.42	Nov 15, 2007
2006	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,256.48	Nov 15, 2006
2005	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,233.40	Nov 15, 2005
2004	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$1,252.25	Nov 15, 2004
2003	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$686.00	Nov 15, 2003
2002	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$658.17	Nov 15, 2002
2001	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$653.89	Nov 15, 2001
2000	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$471.88	Nov 15, 2000
1999	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$486.16	Nov 15, 1999
1998	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$471.63	Nov 15, 1998
1997	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$476.34	Dec 15, 1997
1996	ADVALOREM	\$0.00	\$0.00	\$0.00	\$0.00	\$556.29	Nov 15, 1996
Total		\$0.00	\$0.00	\$0.00	\$0.00		



After recording return to:  
Linda K. Pickthorne  
130 Kitty Drive  
Eagle Point, OR 97524

Until a change is requested all tax  
statements shall be sent to the  
following address:  
Linda K. Pickthorne  
130 Kitty Drive  
Eagle Point, OR 97524

File No.: 7161-3973222 (SDB)  
Date: July 13, 2022

THIS SPACE RESERVED

Jackson County Official Records **2022-026174**  
**R-WD**  
Stn=62 HALLEH **08/25/2022 02:13:02 PM**  
\$15.00 \$10.00 \$11.00 \$11.00 \$60.00 **\$107.00**  
I, Christine Walker, County Clerk for Jackson County, Oregon, certify  
that the instrument identified herein was recorded in the Clerk  
records.  
Christine Walker - County Clerk

### STATUTORY WARRANTY DEED

**Courtney Munson**, Grantor, conveys and warrants to **Linda K. Pickthorne**, Grantee, the following described real property free of liens and encumbrances, except as specifically set forth herein:

See Legal Description attached hereto as Exhibit A and by this reference incorporated herein.

**Subject to:**

1. Covenants, conditions, restrictions and/or easements, if any, affecting title, which may appear in the public record, including those shown on any recorded plat or survey.
2. The **2022-2023** Taxes, a lien not yet payable.

The true consideration for this conveyance is **\$425,000.00**. (Here comply with requirements of ORS 93.030)

BEFORE SIGNING OR ACCEPTING THIS INSTRUMENT, THE PERSON TRANSFERRING FEE TITLE SHOULD INQUIRE ABOUT THE PERSON'S RIGHTS, IF ANY, UNDER ORS 195.300, 195.301 AND 195.305 TO 195.336 AND SECTIONS 5 TO 11, CHAPTER 424, OREGON LAWS 2007, SECTIONS 2 TO 9 AND 17, CHAPTER 855, OREGON LAWS 2009, AND SECTIONS 2 TO 7, CHAPTER 8, OREGON LAWS 2010. THIS INSTRUMENT DOES NOT ALLOW USE OF THE PROPERTY DESCRIBED IN THIS INSTRUMENT IN VIOLATION OF APPLICABLE LAND USE LAWS AND REGULATIONS. BEFORE SIGNING OR ACCEPTING THIS INSTRUMENT, THE PERSON ACQUIRING FEE TITLE TO THE PROPERTY SHOULD CHECK WITH THE APPROPRIATE CITY OR COUNTY PLANNING DEPARTMENT TO VERIFY THAT THE UNIT OF LAND BEING TRANSFERRED IS A LAWFULLY ESTABLISHED LOT OR PARCEL, AS DEFINED IN ORS 92.010 OR 215.010, TO VERIFY THE APPROVED USES OF THE LOT OR PARCEL, TO DETERMINE ANY LIMITS ON LAWSUITS AGAINST FARMING OR FOREST PRACTICES, AS DEFINED IN ORS 30.930, AND TO INQUIRE ABOUT THE RIGHTS OF NEIGHBORING PROPERTY OWNERS, IF ANY, UNDER ORS 195.300, 195.301 AND 195.305 TO 195.336 AND SECTIONS 5 TO 11, CHAPTER 424, OREGON LAWS 2007, SECTIONS 2 TO 9 AND 17, CHAPTER 855, OREGON LAWS 2009, AND SECTIONS 2 TO 7, CHAPTER 8, OREGON LAWS 2010.

Dated this 12 day of August, 2022.

Courtney Munson  
Courtney Munson

STATE OF Oregon )  
County of Jackson )ss.

This instrument was acknowledged before me on this 12<sup>th</sup> day of August, 2022 by **Courtney Munson**.

Katie Lyn Hirunpugdi  
Notary Public for Oregon  
My commission expires: 08/19/2023



APN: 1-022323-1

Statutory Warranty Deed  
- continued

File No.: 7161-3973222 (SDB)

**EXHIBIT A**

**LEGAL DESCRIPTION:** Real property in the County of Jackson, State of Oregon, described as follows:

**LOT 1 IN BLOCK 1 OF LONG BRANCH SUBDIVISION, IN JACKSON COUNTY, OREGON,  
ACCORDING TO THE OFFICIAL PLAT THEREOF, RECORDED IN VOLUME 11, PAGE 30, PLAT  
RECORDS.**



4900  
2.83 Ac.

4800  
6.17 Ac.

4400  
1.75 Ac.

4500  
1.07 Ac.

4600  
1.06 Ac.

4700  
1.02 Ac.

4100  
1.14 Ac.

4000  
1.17 Ac.



CS-3804

CS-5037

KITTY DRIVE

LONG

W 20

# Well Information



## B3 Pump - Well Inspection & Flow Test

Phone: (541)-630-0800

CCB# 240724

### Customer Information

Property Address	130 Kitty Dr	Date	6/4/2026
Technician	Ryan Buma		

Elapsed (Hr)	Flow (GPM)	Water Level (ft)	Notes
0	12	90	
0.25	11.5	127	
0.5	11	130	
0.75	11	133	
1	11	133	
1.25	11	133	
1.5	11	133	
1.75	11	138	
2	11	138	
2.25	11	138	
2.5	11	138	
2.75	11	138	
3	11	138	
3.25	11	138	
3.5	11	138	
3.75	11	138	
4	11	138	

### Summary

Avg Flow GPM	11.1
Min Flow GPM	11.0
Max Flow GPM	12.0

### Well Information

Well Depth (ft)	NA	Static Water Level	90	Pump Depth (ft)	NA
Casing Size	6"	Well Type	Domestic	Wellhead Condition	Ok

### Pump System

Pump Type	Submersible	Pump HP	3/4 HP	Voltage	240 V
Control Type	Pressure Switch	Tank Size	81	Tank Condition	Good
Motor AMP's	NA				

### Flow Test Summary

Test Duration (hrs)	4 HR	Flow Rate (GPM)	11.08823529	Static (ft)	90
Drawdown (ft)	48	Recovery Time	NA		

### Water Quality / Condition

Clarity	Clear	Odor	None	Sediment Present	None
---------	-------	------	------	------------------	------



## B3 Pump - Well Inspection & Flow Test

Phone: (541)-630-0800

CCB# 240724

### Customer / Realtor Summary

The well produced around 11GPM for the entirety of the test, this is suitable for normal house hold use and landscaping. The well system has a uv unit inside the pump room. The bulb and filter will need to be replaced annually.

### Findings / Notes

Flow testing did not induce full drawdown to the pump intake. The well maintained recovery throughout the test, indicating the measured flow rate reflects pump limitations rather than well capacity, and actual well yield is likely higher.

### Recommended Repairs

NA



# Grants Pass Water Lab

"Fast & Reliable Water Testing Since 1978"

964 SE M Street · Grants Pass, OR 97526 · 541-476-0733 · [www.gpwaterlab.com](http://www.gpwaterlab.com) · ORELAP# OR100033

**Mail To:**

**B3 Pump**

Attn: Ryan Buma  
1285 Wards Creek Dr  
Rogue River, OR 97537

Date: June 08, 2026  
Address of Source: 130 Kitty Rd  
Sample ID #: 22601783  
Project Name: None Provided

## Analysis Report

The following results pertain only to the samples submitted, and are for the sole and exclusive use of the above named client.

This report shall not be reproduced, except in full, without written approval of the laboratory.

The following accredited results meet all requirements of ISO/IEC17025:2005 unless otherwise noted by data flag indicators or comments.

The color coded key is only a guide for interpreting results. All evaluations should be compared to the limitations set by the EPA and/or your primary care physician.

Please do not hesitate to call to discuss results or ask any questions. We are at your service!

Sincerely,

Doree Schaafsma  
Laboratory Director

## Sample Information

Sample ID: <b>22601783</b>	Collectors Name: Ryan Buma
Address of Source: 130 Kitty Rd	Sample Point: Well Tap
Project Name: None Provided	Source: Well
Received Date: 06/05/2026	Treatment System: UV Light

## Microbiological (Bacteria) Results

Sample Notes:		Collection Date: <b>06/04/26 11:45 AM</b>					
Contaminate	Method	RESULTS	Units	Date Analyzed	Analyst	ID	Data Flags
Total Coliform	COLILERT	<b>Absent</b>	100ml	6/5/2026 4:23:47 PM	ADS	AC	A
E. Coli	COLILERT	<b>Absent</b>	100ml	6/5/2026 4:23:47 PM	ADS		

### This Sample DOES Conform

For samples which do not conform the presence of total coliform bacteria may indicate surface contamination. Although total coliforms are generally harmless, such water is potentially unsafe. In such cases chlorinate the system and resample in 7 days.

See chlorination instructions on the web at: <http://www.gpwaterlab.com/well-chlorination.asp>.

The results of analyses on water samples can only be as good as the sample submitted to the lab. The laboratory examination determines the presence or absence of contamination in the submitted sample only; therefore, no definite conclusions should be drawn from a single test.

## Results of Chemical Analysis

Sample Notes:		Collection Date: <b>06/04/26 11:45 AM</b>								
Contaminant	Method	LOQ	RESULTS	Units	EPA Limit	Date Analyzed	Analyst	ID	Data Flags	
Arsenic	SM 3113 B	0.005	<b>0.0093</b>	mg/L	0.01	06/05/26 1:31 pm	PVS	AA	A	
Nitrate	EPA 300.0	0.5	<b>ND</b>	mg/L	10	06/06/26 10:18 pm	PVS	AB	A	

#### DEFINITIONS AND DATA FLAGS

A Analysis is covered under ORELAP scope of Accreditation AA Analysis is covered under ISO scope of Accreditation C Sample did not meet acceptance criteria H Analysis performed outside method hold time ID Subsample identifier for each Sample number M Matrix Spike recovery is out of control limits due to matrix interference The LCS was in acceptance limits showing the analysis is in control and the data is acceptable	E Estimated Value LOQ Reporting Limit N/A Not Applicable ND None Detected S Sample Outsourced
---	---

<b>Results Color Key</b>
<b>White - No EPA Limit</b>
<b>Low Risk within EPA Limit</b>
<b>Medium Risk</b>
<b>High Risk Exceeds EPA Limit</b>
<b>Call the Lab to Discuss</b>

# Septic Information

# Septic Evaluation

for the property located at:

**130 Kitty Drive  
Eagle Point, OR 97524  
Jackson County**

Prepared by:



**Sweet Water Sanitation, llc**

1736 Avenue F

White City, OR 97503

541-821-1426

[www.swsmodoc.com](http://www.swsmodoc.com)

**“Our Service is the Difference”**



# Sweet Water Sanitation, LLC.

1736 Avenue F White City, OR 97503 Phone: **541-821-1426** Web: [www.swsmodoc.com](http://www.swsmodoc.com)

---

The information we gather to complete this report comes from a variety of sources. Every step is taken to make this report as accurate as possible at the time of inspection.

#### Sources we use:

- 1) County / DEQ Records either via email, online, or in person
- 2) Internet sources such as Google, Zillow, MLLS, or Realtor sites.
- 3) GPS, onX Hunt
- 4) Buyer, Seller and / or representative.

**Records:** We may edit County or DEQ records, removing only blank pages or pages that do not have any connection with the septic system. We try to include all relevant information we have access to.

#### Inspectors:

Our inspectors hold either an Installers License or Maintenance Providers License from the State of Oregon. Our inspectors attend regular Continuing Education Classes to keep up to date with their license and new system designs. We have over 20 years combined experience in the Septic industry. We are members of Oregon Onsite Wastewater Association and Part of Oregon Septic Smart.

#### Recommendations:

Not all recommendations made in the inspection are required to be completed. We will make some recommendations to simplify the access to the system or to save money for the customer in the future. These recommendations are not required to allow the system to function. We will also make recommendations that may need to be completed. Example given, having a sand filter flushed by a professional Maintenance Provider if it has never been serviced. The septic system does not have to meet current codes. We are evaluating it as it exists. The completion of recommendations should be at the discretion of the buyers and sellers.

#### Disclaimer:

This evaluation report describes the septic system as it exists on the date of evaluation and to the extent that components and operation of the system are reasonably observable. The system may not meet current codes but it should meet the codes as of when it was installed. DEQ recognizes that this evaluation report does not provide assurance or any warranty that the system will operate properly in the future.



OREGON ONSITE  
WASTEWATER ASSOCIATION





# Sweet Water Sanitation, LLC.

1736 Avenue F White City, OR 97503 Phone: 541-821-1426 Web: [www.swsmodoc.com](http://www.swsmodoc.com)

---

## Helpful Information for Septic Systems

The average life span for septic systems is between 20 and 40 years. Concrete tanks can last longer than the septic system.

Older tanks with cast iron or metal baffles will eventually need the baffles replaced. The iron corrodes and will shut down the draining of the tank.

Steel tanks have a life expectancy of about 25 years. Though a tank may still be functioning at the time of an inspection, there may be corrosion that may not be visible. A functioning steel tank is a tank that is not leaking or in danger of collapsing.

Drain fields should be protected from vehicles, livestock and deep-rooted plants. It is not advised to water the ground where the drain field is located.

Sand filter systems (prior to 2014) though they may not require a maintenance provider for annual service, they should be flushed out by a maintenance provider. This may require monitoring ports to be exposed if they are not currently exposed. Yearly service is best, at least every other year is advisable.

Sand Filters (2014 and newer) and Advanced Treatment Technology systems require a maintenance provider and must be inspected yearly, and a permit renewed every year. A maintenance provider is required on these systems for the life of the septic system.

Septic tanks should be pumped every 3-5 years depending on the number of people living in the house. Pumping the tank is required to remove the solids from the tank. Neglected tanks allow solids to travel into the drain field which will shorten the life of the drain field. Septic additives Do Not change the pumping frequency.

Accessibility to the septic tank. Care should be taken to keep the tank accessible for a pumper truck. If the septic pumper truck cannot reach the septic tank in a reasonable fashion, it will increase the cost for service or make it difficult to service.

Risers should be installed to tanks if the lids are not to ground level. Though the lids may not coincide with all landscapes, they ease access to the tank for service and to ease diagnosing issues that may arise with septic systems.

This information is added to help owners, there may be varying opinions on each topic. DEQ recognizes that this evaluation report does not provide assurance or any warranty that the system will operate properly in the future.

“Our Service is the Difference”



# Sweet Water Sanitation, LLC.

1736 Avenue F White City, OR 97503 Phone: 541-821-1426 Web: [www.swsmoc.com](http://www.swsmoc.com)

---

## Septic Tank Lid Safety

### **Avoid Injury or a Tragedy**

People do accidentally fall into septic tanks. In most cases, the person who falls in gets out without serious injury. But a child's tragic death is a reminder to inspect your septic system for damaged or missing lids.

Take these precautions to make sure no one accidentally falls into your septic tank.

Know where your septic system lids or covers are located.

Routinely inspect the condition of the lids for hazards or problems.

Keep the lids secure by repairing or replacing all damaged or missing parts.

Use bolts, screws, or other locks to secure the lids and prevent easy access.


Never drive or park vehicles on top of septic systems – it can damage or dislodge the cover.

Never leave an open lid unattended when inspecting or having your septic system pumped. Make sure the lids are secured after working on your septic system.

Teach children that the septic tank lids are not to be played on or opened.

Contact a septic professional if you notice a depression forming in the septic area.

Owners of septic systems are responsible for ensuring the systems are safe and function properly, including having a secure lid on the tanks.





Sweet Water Sanitation, llc

1736 Avenue F

White City, OR 97503

# Sales Receipt

Date	Sale No.
5/29/2026	SWS 7186

Phone #	541-821-1426 or 541-821-2907
---------	------------------------------

Sold To
Linda Perdue 130 Kitty Dr. Eagle Point, OR 97524

Check No.	Payment Method	Project
1116		

Description	Qty	Rate	Amount
Septic Pumping 130 Kitty Dr. Eagle Point, OR 1250-1500 Gals.		630.00	630.00
Septic Inspection		350.00	350.00
<b>Total</b>			\$980.00

www.swsmodoc.com



## Existing System Evaluation Report for Onsite Wastewater Systems

State of Oregon Department of Environmental Quality  
Onsite Program  
165 East Seventh Ave, Suite 100  
Eugene, OR 97401

Please answer the following questions completely. Do not leave any blank responses. Write unknown if unknown. Refer to Oregon Administrative Rule 340-071-0155 for more information, and please visit: <http://www.oregon.gov/deq/Residential/Pages/Septic-Smart.aspx>

### Septic System Owner-Provided Information:

Property Owner(s)(Sellers): Linda Perdue Telephone: \_\_\_\_\_

Site Address: 130 Kitty Drive City: Eagle Point Zip Code: 97524

County: Jackson Lot Size: 1.02 Acres/Square Feet (circle units)

Legal Description: T:34 R:1W S:20A Taxlot:4700

Age of wastewater treatment system 42 (years) Is there a service contract for system components? No

Date the septic tank was last pumped 2019? (please attach receipt if available)

Number of people occupying dwelling 2 If unoccupied, for how long has it been vacant? N/A

Was this section completed by the evaluator because owner or agent was unavailable? Yes

**The above information is true and to the best of my knowledge.**

\_\_\_\_\_  
Date (MM/DD/YYYY)

\_\_\_\_\_  
Signature of Owner, or agent if present

Name of person performing evaluation (please print): Kevin Riddle

Certification:

- |   |  |
|---|--|
| <input checked="" type="checkbox"/> Installer                                   | <input type="checkbox"/> Professional Engineer           |
| <input type="checkbox"/> Maintenance Provider                                   | <input type="checkbox"/> Environmental Health Specialist |
| <input type="checkbox"/> National Association of Wastewater Technicians         | <input type="checkbox"/> Waste Water Specialist          |
| <input type="checkbox"/> Other: DEQ approved in writing (please describe) _____ |  |

Certification Number: RI 749 SDS 38907

Business name Sweet Water Sanitation, llc Email kevin@swsmodoc.com

Business address 1736 Avenue F White City, OR 97503 Phone 541-821-1426

Date of Evaluation: 05/29/2026 9:26-10:25 (MM/DD/YYYY)

**I hereby certify, by my signature, that I meet all of the qualifications required to perform onsite wastewater system evaluations in the state of Oregon pursuant to OAR 340-071-0155.**

05/29/2026

\_\_\_\_\_  
Date (MM/DD/YYYY)

Kevin Riddle  
\_\_\_\_\_  
Signature of Qualified Septic System Evaluator

## Oregon Department of Environmental Quality

1. **General System Information**

The Existing System Evaluation Report form contains 8 pages. Some of the questions on this form may not pertain to the system being evaluated, as there are many system designs. If you (the septic system evaluator) are unable to answer any of the questions on this form please indicate, in writing, why this information was not available at the time the evaluation was completed.

- The existing septic system consists of (check all that apply):

- |  |  |
|--|--|
| <input type="checkbox"/> Septic Tank                       | <input type="checkbox"/> Cesspool                                  |
| <input type="checkbox"/> Dosing Tank                       | <input checked="" type="checkbox"/> Disposal Trenches/ Leach Lines |
| <input checked="" type="checkbox"/> Multi-compartment Tank | <input type="checkbox"/> Capping Fill                              |
| <input type="checkbox"/> Seepage Bed                       | <input checked="" type="checkbox"/> Sand Filter                    |
| <input type="checkbox"/> Other _____                       |  |

**Note:** Cesspools may be used only to serve existing sewage loads and if failing only be replaced with a seepage pit system on lots that are too small to accommodate a standard system or other alternative onsite system.

There is a permit for the septic system Yes No Unknown

- Permit Number(s) 15-138-84N
- Year original septic system installed: 1984 (YYYY) No record of installation date
- Dates of subsequent repairs or alterations: \_\_\_\_\_ (YYYY)
- All plumbing fixtures are connected to the septic system Yes No Unknown

If you answered "No" or "unknown," please describe below:

---



---

- Additional Comments:

There may be a leaking fixture, there was a slow steady drip into the tank. Gave owner dye tabs to test toilets just incase.

2. **Overall Septic System Status**

- Discharge of sewage to the ground surface Yes No None observed
- Discharge of sewage to surface waters Yes No None observed
- Sewage backup into plumbing fixtures Yes No Unknown

- Additional Comments:

Recent Rain. Power to system was off at arrival, turned circuit breaker on and system started

3. **Septic tank**

In order to fully describe the condition of the tank, the septic tank may need to be pumped. Please indicate below if the septic system tank was pumped during the course of *this* evaluation.

- Septic tank was pumped during the course of *this* evaluation Yes No
- If the septic tank was **NOT pumped** during the course of *this* evaluation, please explain (e.g. septic system owner declined to have the tank pumped etc):

## Oregon Department of Environmental Quality

- 
- 
- The septic tank material is:

- Concrete
- Steel
- Plastic
- Fiberglass
- Other (explain) \_\_\_\_\_
- Unknown

- Is the septic tank accessible?  Yes  No
- Septic tank volume in gallons 1500
- Tank volume determined by: Check all that apply, add comments below as needed  
 Permit Records  Measured  Stamped on Tank  Other
- Septic tank risers are at ground level  Yes  No
- Tank appears to be free from defects, leaking and signs of deterioration  Yes  No  
If you answered "No," please describe the condition of the septic tank below. For example, evidence of gas corrosion, cracks, leaks, etc.

Deck is over the first lid, have to remove lattice to access, Tank is at grade.

---

- Septic tank lid(s) is intact  Yes  No
  - Septic tank baffles are intact: Inlet  Yes  No Outlet  Yes  No
  - Baffle material - Inlet  Plastic  Concrete  Metal Outlet  Plastic  Concrete  Metal
  - Effluent filter is present  Yes  No **System does not use**
  - Effluent filter is free of debris  Yes  No  Not Applicable
  - Liquid level in tank relative to invert of outlet  At  Above  Below  
If above or below invert outlet, please explain: \_\_\_\_\_
  - Scum** layer 2-3 (inches)      **Sludge** layer 5-6 (inches)
  - Scum** and **Sludge** layer more than 35% of the *total* tank volume  Yes  No  
Indicate where sludge measured from:  Inlet  Middle  Outlet
  - Additional Comments:
- 

#### 4. Dosing tank / Pump Basin

Dosing tanks use a pump to send effluent to a treatment unit or a soil absorption field.

- The septic system has a dosing tank  Yes  No  
(If "No," skip the rest of section 4)
- At the time of this evaluation the power was on to test the pump(s):  Yes  No

## Oregon Department of Environmental Quality

- Dosing tank capacity 500 (gallons)
- Tank volume determined by: Check all that apply, add comments below as needed  
 Permit Records  Measured  Stamped on Tank  Other
- Dosing tank material Concrete
- Dosing tank appears to be watertight and in good condition  Yes  No
- Dosing tank lid is intact  Yes  No **Wires come out of concrete lid corner**
- Electrical components are sealed and watertight  Yes  No
- Pump/ siphon is functional  Yes  No **Appears to pump slower than it should**
- Type of Pump  Demand dose  Time dose
- Pump control mechanism is functional (floats, pressure transducer)  Yes  No
- There is a high water alarm  Yes  No
- The high water alarm (audible and visual) is working  Yes  No  Not Applicable
- Type of screen Mesh basket
- Screen is clean and free of debris  Yes  No - Screen cleaned for this evaluation  Yes  No
- Scum/ sludge present in Dosing tank  Yes  No
- **Scum** layer 0 (inches)      **Sludge** layer 2-3 (inches)
- Additional Comments:  
This is the second compartment of the septic tank, this is not a separate tank. See note regarding the pump (above)

5. **Soil absorption system**

The soil absorption system is a set of trenches that receives effluent from the septic tank and filters the effluent before it enters the groundwater.

- The septic system has a soil absorption system  Yes  No  Unknown
- Was the soil absorption system part of the evaluation?  Yes  No  See note below  
 If the soil absorption system was not evaluated, please explain below (for example unable to locate, client did not authorize this part of the evaluation):  
Visual Inspection Only.
- Absorption distribution  Equal  Serial  Pressure  Equal via pressure
- Absorption lines construction material:  
 Gravel and pipe  Chamber  Tile  Polystyrene foam and pipe  Other \_\_\_\_\_
- Absorption distribution unit(s):  dropbox  hydrosplitter  equal distribution box
- Intact  Damaged  N/A
- Absorption distribution unit(s) are free of debris or solids  Yes  No  N/A

Oregon Department of Environmental Quality

- Locate all drain lines in soil absorption system Yes No

Total length of drain lines 150 (ft)

Lengths determined by Physically uncovering portions of system/probing Written records

Fish tape Electronic locator  camera

- Absorption area appears to be **free** from roads, vehicular traffic, structures, livestock, deep-rooted plants etc.  
Yes No

If you answered "No," please describe below:

Evidence of vehicles possibly on the end of drain field. Chicken coop may be over part of the drain field.

- Absorption area appears to be **free** from surface water runoff and down spouts Yes No
- Evidence of ponding in absorption area or distribution unit(s) Yes No
- The soil absorption system replacement area assigned in the permit record appears to be intact:  
Yes No  Replacement area not identified in permit record

If you answered "No," please explain below:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

- Additional Comments:  
Visual Inspection Only.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

6. **Sand Filter System**

There are different sand filter system designs used in Oregon. Not every sand filter system will contain all of the components mentioned below, e.g. pumps. The owner of a sand filter system **permitted on or after January 2, 2014 must** maintain an annual service contract with a certified Maintenance Provider. Maintenance records should be available from the system owner, or the contracted Maintenance Provider. **Please attach copies of the previous two years of maintenance records to this evaluation form.**

- The septic system has a sand filter Yes No

(If "No," skip the rest of section 6)

- Type of sand filter

Intermittent  
 Recirculating  
 Bottomless

- Sand filter container appears free from defects, leaks and signs of deterioration: Yes No

Oregon Department of Environmental Quality

- Sand filter unit appears to be **free** from roads, vehicular traffic, structures, livestock, deep-rooted plants etc.

Yes No

If you answered “No,” please describe below:

---



---



---

- Sand filter appears to be **free** from surface water runoff and down spouts Yes No
- Evidence of ponding in/ on sand filter media surface Yes No
- Surface access to manifold and valves Yes No
- Monitoring ports are present Yes No
- Lateral lines flushed and equal distribution verified Yes No
- The sand filter has a pump Yes No

(If “No”, skip the rest of section 6)

- Pump vault appears to be watertight and in good condition Yes No N/A
- Pump is functional Yes No
- Pump control mechanism is functional (floats, pressure transducer) Yes No
- High water alarm in pump vault (audible and visual) is working Yes No
- Pump electrical components are sealed and watertight Yes No

- Additional Comments:

Recommend monitor ports be exposed to allow system to be flushed in the future.

---



---



---

7. **Alternative Treatment Technology System**

The owner of an ATT system *must* maintain an annual service contract with a certified Maintenance Provider. Maintenance records should be available from the system owner, or the contracted Maintenance Provider. **Please attach copies of the previous two years of maintenance records to this evaluation form.**

**Note\*** Some ATT systems may have a WPCF permit. Please contact the local Health Department or the DEQ to obtain a copy of the WPCF permit.

- The septic system has an **Alternative Treatment Technology (ATT)** Yes No  
(If “No,” skip the rest of section 7)
- Please provide the product name, system ID number, and manufacturer name below:

Product name \_\_\_\_\_  
 System ID number \_\_\_\_\_  
 Manufacturer name \_\_\_\_\_

Oregon Department of Environmental Quality

- Previous two years of maintenance records are available  Yes  No  
If you answered “No,” please explain below:

---



---

- Previous two years of maintenance records are attached to this form  Yes  No  
If you answered “No,” please explain below:

---



---

- Additional Comments:

---



---



---

8. **Please attach a copy** of the following items to this form. Contact the DEQ, or the local Health Department to locate these items.

- The septic system permit(s) to this form, if available
- The as-built drawing(s) to this form, if available
- The Certificate of Satisfactory Completion to this form, if available
- Additional Comments:  
County / DEQ records are attached.

---



---

We may add Arc-GIS and Section maps to some files if we think they are helpful.

---

9. **Provide a Site Plan**

- Please provide a sketch of the complete system (show only system components that were evaluated) on page 8 of this form, if a copy of the original “as-built” drawing is *not* available.
- Please provide a sketch of the complete system on page 8 of this form if the original “as-built” drawing is *not* accurate or representative of the existing system.
- If the original “as-built” drawing is available for copy, and the original appears to be accurate and representative of the existing system, write “see attached as-built” on page 8 of this form, redrawing the system is unnecessary.
- Additional Comments:  
A site plan is attached and appears accurate, this replaces page 8 of this report.

---



---

An image is attached showing estimated layout of the system.

---

10. **Disclaimer:**

This evaluation report describes the septic system as it exists on the date of evaluation and to the extent that components and operation of the system are reasonably observable. DEQ recognizes that this evaluation report does not provide assurance or any warranty that the system will operate properly in the future.

- 11. I hereby certify, by my signature, that the above information and the plot plan on the next page of this form are accurate and true to the best of my knowledge.

05/29/2026

Date

*Kevin Riddle*

Signature of Qualified Septic System Evaluator

Oregon Department of Environmental Quality

**Provide a Site Plan in the space below:** Show the actual or best estimate measurements of components that were confirmed during this evaluation; septic tank, soil absorption system, property lines (if known), easements (if known), existing structures, driveways, and water supply (water lines and wells). **Draw to scale and indicate the direction north.**

A large grid area for drawing a site plan. The grid consists of 30 columns and 30 rows of small squares, providing a space for the user to draw and measure site components as instructed in the text above.



# Sweet Water Sanitation, LLC.

1736 Avenue F White City, OR 97503 Phone: 541-821-1426 Web: [www.swsmoc.com](http://www.swsmoc.com)

May 29, 2026

## Septic Evaluation


### 130 Kitty Dr. Eagle Point, OR Jackson County



**Inlet Baffle**



**Interior Outlet Baffle**



**Dosing Tank / Pump System**



**View of Lids to House**

Pictures Page 1 of 2

This report is not a guarantee of the life of the drain field or continuous satisfactory operation of the onsite disposal system



# Sweet Water Sanitation, LLC.

1736 Avenue F White City, OR 97503 Phone: 541-821-1426 Web: [www.swsmodoc.com](http://www.swsmodoc.com)

---

May 29, 2026

## Septic Evaluation

### 130 Kitty Dr. Eagle Point, OR Jackson County



**View of Sand Filter from Tank**



**View of Drain Field from end of Sand Filter**

Pictures Page 2 of 2

This report is not a guarantee of the life of the drain field or continuous satisfactory operation of the onsite disposal system

sand filter

Drain Field

Septic Tank



MUNSON COURTNEY

Address ✕  
**130 Kitty Drive, Eagle Point, Oregon 97524, United States**

Overview    Hunt Unit    Weather

📍 Coordinates 42.60047, -122.83853 Copy



ZONING CLEARANCE SHEET

ROADS, PARKS AND PLANNING SERVICES • 10 S. OAKDALE AVE., RM. 100 • MEDFORD, OREGON 97501-2902 • (541) 774-6900

9/27/01 11:38:00

PLZN200R

File Number: 2001 1407 ZCS

Current Owner: MAY V JOAN

Map Id: 341W20 Tax Lot: 2102 Acreage: 1.02
Property Address: 130 KITTY DR Acres: 1.02

Applicant Name: MAY V JOAN
Mailing Address:
City/St: Phone:
Zoning Clearance Date: 9/27/2001 Creation Date:

Proposal: INFORMATION

To Serve: SETBACKS/PROPOSED TMH

\*\*\*\*\*

Property is Zoned: RR-5 Minimum Parcel Area: 5 ACRES
MINIMUM STRUCTURAL SETBACK FROM PROPERTY LINES: Front: 30 Side: 20 Rear: 20

Development on this land is subject to Mandatory Fire Safety Requirements as described in Chapter 280.100 of the Jackson County Land Development Ordinance. A 100 foot fuelbreak is required and may affect setbacks.

This property lies in a NONRESOURCE zoning district and abuts a RESOURCE zoning district. Special setbacks of 200 feet from the resource lands to the SOUTH are required for dwellings unless an exception is approved by staff.

Comments:

THE PROPOERTY OWNER CALLED AND INQUIRED ABOUT THE POSSIBILITY OF GETTING A TMH PERMIT APPROVED TO MOVE A CAREGIVER ONTO THE PROPERTY. THE LOT IS A NON-CONFORMING LOT CREATED BY 1983-116-LLA. THE LOT IS ABOUT 215' X 230' AND HAS AN EXISTING DWELLING. THE LOT IS TOO SMALL TO SUPPORT THE REQUIRED 100' FUELBREAK REQUIRED FOR THE RR-5 ZONE. A FUELBREAK REDUCTION WOULD BE REQUIRED IN ORDER TO PLACE A TEMPORARY MOBILE HOME ON THE PROPERTY. A FUELBREAK REDUCTION APPLICATION AND A TEMPORARY MEDICAL HARDSHIP APPLICATION WERE SENT TO THE PROPERTY OWNER.

5.10.2008: Developed Vernal pools mapped. outside UGB of Shady Cove.

ms.may has inquired about parking an RV on property. Looking to power + water, + using RV as a possible "den", or "computer room". No eating, sleeping, or cooking is proposed in RV.

CERTIFICATION: The information I have provided for this zoning clearance is, to the best of my knowledge, true, accurate and complete. I also understand that any changes in my plans or county regulations may render this clearance sheet invalid.

Signature of owner/applicant: \_\_\_\_\_ Date: \_\_\_\_\_
Signature of staff member: Dan Segar \_\_\_\_\_ Date: 9-27-01

Copy of the zoning clearance MAILED to applicant on: 9/27/2001

Use of RV is limited to 30 days in 12 mo. period. OR 1yr. TMH use with TMH application approval.

05.08.03: Parcel is bordered on West, South + East Side by an ~~existing~~ improved public road. Minimum structural setbacks required only. 100' fuelbreak required on North Side.

Handwritten text, possibly bleed-through from the reverse side of the page. The text is illegible due to fading and low contrast.

Handwritten text, possibly bleed-through from the reverse side of the page. The text is illegible due to fading and low contrast.

Handwritten text, possibly bleed-through from the reverse side of the page. The text is illegible due to fading and low contrast.

STATE OF OREGON

DEPARTMENT OF ENVIRONMENTAL QUALITY

AUTHORIZATION NOTICE

OWNER Paul D. Andrest DATE ISSUED: 5 MAR 87  
 PROPERTY ADDRESS 130 Kitty Drive, Shady Cove DATE EXPIRED: 5 MAR 88  
 TYPE OF SEPTIC SYSTEM Sand Filter  
 TOWNSHIP 34 RANGE 1W SECTION 20 TAX LOT 2102

THIS AUTHORIZATION NOTICE ACKNOWLEDGES THAT THE SEWAGE SYSTEM LOCATED ON THE PROPERTY IDENTIFIED ABOVE APPEARS ADEQUATE, ON THE BASIS OF A record review, TO SERVE A (FIELD INSPECTION OR RECORD REVIEW)

four (4) bedroom single family dwelling WITH A SEWAGE FLOW UP TO (# BEDROOMS AND TYPE STRUCTURE)  
450 GALLONS PER DAY.

SPECIAL CONDITIONS OF APPROVAL:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

ROUTINE MAINTENANCE SHOULD INCLUDE PUMPING OF THE SEPTIC TANK EVERY 3 to 5 YEARS.

B. H. ... R.S.  
 SANITARIAN

JACKSON COUNTY

- NOTE:
1. A PERMIT AND INSPECTION OF THE BUILDING SEWER CONNECTION TO THE SEWAGE SYSTEM MAY BE REQUIRED BY THE COMMERCE DEPARTMENT OR ITS AUTHORIZED REPRESENTATIVE.
  2. THIS AUTHORIZATION NOTICE DOES NOT GUARANTEE SATISFACTORY OR CONTINUOUS OPERATION OF THE SEWAGE SYSTEM IDENTIFIED.



SEPTIC/WELL APPLICATION  
SANITATION DIVISION

DEPARTMENT OF PLANNING & DEVELOPMENT • COUNTY COURTHOUSE • MEDFORD, OREGON 97501 • (503) 776-7554

Owner PAUL D. ANDREST Township 34 Range 1W Section 20  
Tax Lot 2102 Acres \_\_\_\_\_

Address (if any) and Directions to Property 130 KITTY DR.  
SHADY COVE OR.

Site Evaluation Fee \_\_\_\_\_ Minus Preliminary Site Fee \_\_\_\_\_ Balance to be Paid \_\_\_\_\_  
Number of Sites \_\_\_\_\_ Receipt # \_\_\_\_\_ Date \_\_\_\_\_

Permit Application Type Auth. Not Fee 500 Receipt # 0931 Date 3-4-87  
Well Permit Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ Date \_\_\_\_\_

Proposed Residence or Business? Replacement # Test Holes Ready \_\_\_\_\_ Date \_\_\_\_\_  
Any Residence/Business on Lot Now? \_\_\_\_\_  No. of Bdrms/Seats/Employees 3

Pumping Receipt Submitted? \_\_\_\_\_ Tank Uncovered? \_\_\_\_\_ Date \_\_\_\_\_

Comments (if any) \_\_\_\_\_

I certify that the information given is true and correct to the best of my knowledge. OCV ✓

Date 3-4-87 Owner's Signature Paul D. Andrest  
(or representative with written authorization)

1010 D'ANCONIA DR TRAIL OR 97541 ✓ 878-3173  
Mailing Address (#, Street, City, State, Zip Code) Phone No.

-----DO NOT WRITE BELOW THIS LINE-----

Complete Application Date 3-4-87

Site Evaluation Results:

By \_\_\_\_\_ Date \_\_\_\_\_

WELL PERMIT: Approved \_\_\_\_\_ Not Approved \_\_\_\_\_ Date \_\_\_\_\_ By \_\_\_\_\_  
Expires \_\_\_\_\_

Comments: \_\_\_\_\_ Well Permit # \_\_\_\_\_


SEPTIC PERMIT INSTALLATION SPECIFICATIONS: \_\_\_\_\_ Gallon Septic Tank (1250 recommended)  
\_\_\_\_\_ Lineal Feet of Drainfield \_\_\_\_\_

Keep drainfield and approved repair area free of all development, compaction, soil modification,  
traffic, heavy cultivation and fenced from livestock.

PERMIT: Approved  Not Approved \_\_\_\_\_ By BURTON R. S. # \_\_\_\_\_  
Date 5 MAR 87 EXPIRES 5 MAR 88 Final Inspection On \_\_\_\_\_ Installer \_\_\_\_\_

Certificate of Satisfactory Completion Issued \_\_\_\_\_ By \_\_\_\_\_

Comments: \_\_\_\_\_



130 KITTY DR.  
34-1W-20-PARCELS 2102  
PAUL D. + ELAINE A.  
ANDREST  
MOBILE HOME SITE

ROGLIE RIVER DRIVE

3/4/87 cjf --- MH BEING REPLACED



# JACKSON COUNTY OREGON

COUNTY COURTHOUSE • MEDFORD, OREGON 97501

DEPARTMENT OF PLANNING AND DEVELOPMENT  
Kerry L. Lay, Director  
(503) 776-7554

## AUTHORIZATION NOTICE

DATE 3-4-87

RE: TWP 34 RANGE 1W SECTION 20 TAX LOT 2102

I have no information that the existing subsurface sewage disposal system located on the above referenced property has ever failed by discharging sewage upon the ground surface or into public waters, by clogging or backing up, or in any other manner.

The existing system consists of 300 (square feet of drainfield), and last served OR is serving a dwelling having 2 bedrooms (include all rooms that could be used as bedrooms though actually used for other purposes, such as a den or sewing room) OR business (type of)                      consisting of                      (number of employees or occupancy) on currently (date).

To the best of my knowledge, the existing septic tank has a 1500 gallon capacity determined by                      (pumping record, permit, etc).

The existing septic system was installed on 9-6-84 (date) under authority of Jackson County Subsurface Sewage Permit # 15-138-84N.

I intend to connect a dwelling having 3 bedrooms (include all rooms that could be used as bedrooms though actually used for other purposes, such as a den or sewing room) OR business (type of) SEWING RM consisting of                      (number of employees or occupancy) on ASAP (date).

OR: I intend to add to my existing structure (state all rooms to be added)

---

Paul O. Andrew  
Property Owner's Signature

*please see cabinet*



DEPARTMENT OF PLANNING & DEVELOPMENT

# ZONING CLEARANCE SHEET

This clearance sheet provides a Planning staff analysis of your property and development plans, and their relationship to the Jackson County Land Development Ordinance. Land development regulations and your property development plans are both subject to change. When such change does occur, it may invalidate this zoning clearance or otherwise alter conditions of approval.

PROPERTY DESCRIPTION: Township 34, Range 10W, Section 20, Tax Lot 2102, Acres 1.02

PROPERTY ADDRESS: 130 Kitty Dr DATE TAX LOT CREATED: \_\_\_\_\_

OWNER OR APPLICANT: Paul Anderson TELEPHONE: \_\_\_\_\_ ADDRESS: \_\_\_\_\_

PROPOSAL:  First Dwelling  Additional Dwelling  Other - Explain Auth Notice replacement m/H

\*\*\*\*\*  
PROPERTY IS ZONED: RR-5 MINIMUM PARCEL AREA: \_\_\_\_\_

Development on this land is subject to Mandatory Fire Safety Requirements as described in Chapter 280.100 of the Jackson County Land Development Ordinance. Fuelbreak requirements may affect setbacks.

MINIMUM STRUCTURAL SETBACK FROM PROPERTY LINES: Front 30, Side 20, Rear 20

This property lies in a NONRESOURCE zoning district and abuts a RESOURCE zoning district. Special setbacks are required unless an exception is approved by staff.

BEFORE ZONING CLEARANCE CAN BE GIVEN FOR THE ABOVE PROPOSAL, THE OWNER/APPLICANT MUST APPLY FOR AND RECEIVE APPROVAL OF:

- Minor Partition
- Forest Site Plan Review
- Nonforest Site Plan Review
- Commercial Site Plan Review
- Variance
- Alteration of Nonconforming Use
- Major Partition
- Farm/Nonfarm Dwelling
- County Recognized Access
- Administrative Review for Structures in a Floodplain
- Administrative Review for Airport Approach/Concern Area
- Subdivision
- Conditional Use Permit
- Temporary Mobile Home
- Areas of Special Concern Specify \_\_\_\_\_
- Other - See Below

COMMENTS BY STAFF: new home further from ELL on south than existing home. plot plan 3/4/87 DR.

NO CONFLICTS EXIST. The proposed use or development as presented herein is in conformance with the Land Development Ordinance. Falsification of information renders this zoning clearance null and void.


CERTIFICATION: The information I have provided for this zoning clearance is, to the best of my knowledge, true, accurate and complete. I also understand that any changes in my plans or county regulations may render this clearance sheet invalid.

Signature of owner/applicant: \_\_\_\_\_ Date: \_\_\_\_\_

Signature of staff member: CFoland Date: 3/4/87

Copy of this zoning clearance  handgiven  mailed to applicant on: 3/4/87

5' (with dot)  
10 feet from drainage



1" = 50'

SYSTEM CONSTRUCTION REPORT


Permit # 15-138-84N

Name GREGG ADAMS. Twp 34 R. 1W S. 20 T.L. 2102 System Type SF

Address (Location) KITTY LANE

<p align="center"><u>Tanks and Sewer Lines</u></p> <p>Effluent Sewer <u>OK 9-20-84 KC</u>                  Pressure Transport Pipe <u>9-20-84 KC</u>                  Septic Tank Size &amp; Manuf. <u>1500 Gal - Peterson</u>                  Dosing Tank Size &amp; Manuf. _____                  Fittings, Materials &amp; Connections <u>OK</u>                  Tank to House <u>N/A</u>                  Riser(s) <u>Not Needed</u>  <u>BY CHASTAIN</u></p>		<p align="center"><u>Drainfield 9-6-84</u></p> <p>Trench Width <u>24"</u> Staking _____                  Trench Depth <u>24"-30"</u>                  Gravel Depth <u>12"</u>                  Distance Between Lines <u>10'-12"</u>                  Lines Level <u>OK</u> End Caps <u>OK</u>                  Overflows <u>OK</u> Undisturbed Earth <u>OK</u>                  Total Linear Feet <u>150</u> Distance to Well <u>100</u>                  Approved Square Footage <u>300</u>  <u>BY CHASTAIN</u></p>		<p align="center"><u>Curtain Drain (V-Ditch)</u></p> <p>Total Depth _____                  Rock Depth _____                  Visqueen _____                  Screen <u>OK</u>                  V-Ditch <u>OK</u>                  Berm _____</p>			
<p align="center"><u>ETA</u></p> <p>Bed Check _____                  Gravel &amp; Pipe _____                  Cap _____ Depth _____                  V-Ditch/Curtain Drn _____</p>		<p align="center"><u>Sand Filter/Trench 9-20-84</u></p> <p>Staking _____                  Pressure Test <u>OK</u>                  Discharge Height <u>4'</u>                  Filter Fabric _____                  Sand Depth <u>24"</u>                  Backfill <u>18-24" OK</u></p>		<p align="center"><u>Tile Dewatering</u></p> <p>Staking Check _____                  Drnfd Trnchs _____                  Drn Trnch Check _____                  Rck &amp; Pipe in Drn Trnch _____                  Cleanout _____                  Flaggate &amp; Sch 80 Outlet Pipe _____                  Backfill _____</p>		<p align="center"><u>9-20-84 Pump Systems</u></p> <p>Type &amp; H.P. <u>1/3 HYDRO</u>                  Floats: <u>OK</u> Single &amp; Double _____                  Chk Valve <u>OK</u> Antisiphon <u>OK</u>                  Safety Line <u>OK</u>                  Quick Disconnect <u>OK</u>                  Pump off Floor <u>OK</u>                  Alarm <u>OK</u>                  Electrical Permit _____                  Gate Valve <u>OK</u>                  Screened Enclosure <u>OK</u>  <u>BY CHASTAIN</u></p>	
<p align="center"><u>Capping/Fill</u></p> <p>Scarified Surface _____                  Staking _____                  Cap _____ Depth _____                  V-Ditch/Curtain Drn _____</p>		<p align="center"><u>Low Pressure Distribution</u></p> <p>Staking _____                  Pressure Test _____                  Discharge Height _____                  Filter Fabric _____</p>					

SYSTEM CONSTRUCTION DIAGRAM



Corrections Notice Issued

Good Job - well shaped Sand filter cap

CERTIFICATE OF SATISFACTORY COMPLETION

In accordance with Oregon Revised Statute 454.665, this certificate is issued as evidence of satisfactory completion of a subsurface or alternative sewage disposal system at the above location.

Dick Forey  
Sanitarian

10/11/84

Date

Jackson County

REQUEST FOR INSPECTION

ASAP 9-20-84  
 Date Requested Date Reported

15-138-84N GREGG ADAMS  
 Permit Number Owner

CHASTAIN 130 KITTY DR.  
 Contractor Job Site

PRESSURE -  
 Inspection Site

TWP     R     S     TL    

Note: \_\_\_\_\_

REQUEST FOR INSPECTION

9-5-84  
 Date Requested Date Reported

GREGG ADAMS  
 Permit Number Owner

ORAN Chastain 130 Kitty Dr.  
 Contractor Job Site

Dinnerfield  
 Inspection Site

TWP 34 R 16S20 TL 2102

676-4134

Note: \_\_\_\_\_

INTEROFFICE MEMORANDUM - JACKSON COUNTY

TO: Jean Robinson, Planning

DATE: October 3, 1984

FROM: Sherryll Wallace, Public Works

REF: 34-1W-20-2102

RECEIVED

SUBJECT: ROAD APPROACH - PAUL ANDREST

OCT 5 1984

JACKSON COUNTY

Subject approach at 130 Kitty Drive is a pre-existing approach as verified by the Acting General Superintendent. Mr. Andrest will not be required to obtain a Road Approach Permit from this department unless he makes alterations or modifications to the existing approach.

REQUEST FOR INSPECTION

<u>A S A P</u> Date Requested	<u>10-10-84</u> Date Reported	<u>1030</u> <u>AM</u>
<u>15-138-84N</u> Permit Number	<u>Adams</u> Owner	
<u>Chastin</u> Contractor	<u>130 Kitty Ave</u> Job Site	
<u>Fisat</u> Inspection Site	<u>Shady Lane</u>	

TWR34 R/W S 20 TL 2102

Note: \_\_\_\_\_

JACKSON COUNTY DEPARTMENT OF PLANNING & DEVELOPMENT

Medford, Oregon 97501 - 776-7551

Owner Gregg Adams Twp. 34 Range 10 Section 20  
Tax Lot 2102 Code      Acreage 17  
Address/Directions to Property 130 Kitty Dr.

(ALL FEES ARE NON-REFUNDABLE)

Site Evaluation Fee 190<sup>00</sup> Receipt # 3499 No. of Sites 1 Date: 7-27-84  
 Permit Application Fee      Receipt #      Date:       
 New Installation      Repair/Alteration      Sewage Connection       
 Well Permit Fee      Receipt #      Date:     

Proposed Use of Property SED Test Holes Ready YES - 2  
Zoning Cleared      Number of Bedrooms 3  
Comments: Well Drilled too close to current approval  
Please RUSH

I certify that the information given is true and correct to the best of my knowledge.

Date: 7-27-84 Signature: [Signature]  
1225 Water Lake Ave. Medford, Oregon  
Mailing Address (#, Street, City, State, Zip Code) Phone     

\*\*\*\*\* DO NOT WRITE BELOW THIS LINE \*\*\*\*\*

Site Evaluation:       
Based upon information provided us including a soils and topographic report made by Dick Florey on July 30, 1984, we have found your drainfield site to conform with minimum standards for the issuance of a permit to install a Sand Filter alternative sewage disposal system. An installation permit can be issued provided no conflicts exist with zoning requirements. This approved evaluation report shall remain in effect until issuance of a permit to construct unless in the meantime conditions on this or adjacent properties have been altered in any manner which would prohibit issuance of a permit, in which case, this evaluation report shall be considered null and void. Technical rule changes will not invalidate this report.

By: Dick Florey Date: 8/7/84  
WELL PERMIT: Approved      Not Approved      Date      By:       
Comments:      WELL PERMIT #     


SEPTIC PERMIT INSTALLATION SPECIFICATIONS:      Gallon Septic Tank (1250 gallon recommended)  
     Square Feet of Drainfield:     

Keep drainfield and approved repair area free of all development, compaction, soil modification, traffic, heavy cultivation and fenced from livestock.  
PERMIT: Approved      Not Approved      By:      #       
Date:      EXPIRES      Final Inspection On:       
Certificate of Satisfactory Completion Issued:      By:       
Installer:

JACKSON COUNTY SITE EVALUATION WORKSHEET

NAME Gregg Adams

T 34 R 1W Sec. 20 T.L. 2102



Any Special Conditions for Permit:

Position: Hi Terrace Relief: Smooth Scale: 450 Gall/day Trenches 24-36"  
 Ft. Slope: Hi Terrace Side Slope: Lo Terrace Top: Btm Fan: Other Undlt. Hmky.: 1"=100 12" V ditch 50 lined ft/150g 150 lined ft total

Depth	Texture	Structure	Pores	Mottling	Notes: (%Co Frags., Rooting, Depth, R or I, etc.)	Water Table
P 0-9	Wetcl	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis Med Co con	Faint		Depth Type- P TP Slope % Up 8 Down 13
+ 9-24	Comsted Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint	Pit Sloughed in	
P 0-6	Ltcl	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis Med Co con	Faint		Water Table Depth Type- P TP Slope % Up 12 Down 16
+ 6-20	Cl	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint	20" ave to (R) Sub	
# 20-44	Comsted Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint	Varies 18 to 32"	
P 0-8	Ltcl	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis Med Co con	Faint		Water Table Depth Type- P TP Slope % Up 11 Down 19
+ 8-24	Cl	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint	Sub Varies 24-30"	
124-30	Hcl	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint		
330-50	Com Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint		
P 0-11	Cl	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis Med Co con	Faint		Water Table Depth Type- P TP Slope % Up 7 (R) 11" Down 13-14
+ 11-15	Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis Med Co con	Faint		

Additional Notes: #s 0-12 similar  
 12+ (R) 12"

SITE SUITABILITY: SAND FILTER USEABLE AREA: 100x80  
 Site Evaluation By: Stoney Date: 7/30/84 Drawn 8/2/84

- Abbreviations
- Lt. - light
  - H - heavy
  - F - fine
  - Co. - coarse
  - S - sand(y)
  - Si. - silt(v)
  - R - Layer Limiting Effective Soil Depth
  - C - clay
  - L - loam
  - P - pebbles (2mm.-3")
  - K - cobbles (3"-10")
  - St. - stones (+10")
  - V - very
  - Fx - Fractured
  - Seds - Sedimentary
  - HW - Highly Weathered
  - DG - Decomposing Granite
  - RDM - Rapidly Draining material
- Copies: Yes ✓ No

JACKSON COUNTY DEPARTMENT OF PLANNING & DEVELOPMENT

52 WEST STATE STREET  
Medford, Oregon 97501 - 776-7551

Owner Greg Adams Twp. 34 Range 10 Section 20  
Tax Lot 2102 Code \_\_\_\_\_ Acreage \_\_\_\_\_  
Address/Directions to Property CORNER of KITTYPINE + ROUSE RIVER DRIVE.

(ALL FEES ARE NON-REFUNDABLE)

Site Evaluation Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ No. of Sites \_\_\_\_\_ Date: \_\_\_\_\_  
Permit Application Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ Date: \_\_\_\_\_  
New Installation \_\_\_\_\_ Repair/Alteration \_\_\_\_\_ Sewage Connection \_\_\_\_\_  
 Well Permit Fee 10.00 Receipt # 3279 Date: 6-6-84

Proposed Use of Property \_\_\_\_\_ Test Holes Ready \_\_\_\_\_  
Zoning Cleared \_\_\_\_\_ Number of Bedrooms \_\_\_\_\_

Comments: \_\_\_\_\_

*File*

I certify that the information given is true and correct to the best of my knowledge.

Date: 6/6/84 Signature: [Signature]

Mailing Address (#, Street, City, State, Zip Code) 216 Cambridge Ashland OR 97520 Phone 488-2827

\*\*\*\*\* DO NOT WRITE BELOW THIS LINE \*\*\*\*\*

Site Evaluation: \_\_\_\_\_

By: \_\_\_\_\_ Date: \_\_\_\_\_

WELL PERMIT: Approved  Not Approved \_\_\_\_\_ Date 6-JUN-84 By: BWAPrior, R.S.

Comments: To be installed so as to meet all state and county codes. WELL PERMIT # 112-846

Expires 6-6-85

SEPTIC PERMIT INSTALLATION SPECIFICATIONS: \_\_\_\_\_ Gallon Septic Tank (1250 gallon recommended)  
\_\_\_\_\_ Square Feet of Drainfield: \_\_\_\_\_

Keep drainfield and approved repair area free of all development, compaction, soil modification, traffic, heavy cultivation and fenced from livestock.

PERMIT: Approved \_\_\_\_\_ Not Approved \_\_\_\_\_ By: \_\_\_\_\_ # \_\_\_\_\_

Date: \_\_\_\_\_ EXPIRES \_\_\_\_\_ Final Inspection On: \_\_\_\_\_

Certificate of Satisfactory Completion Issued: \_\_\_\_\_ By: \_\_\_\_\_

Installer: \_\_\_\_\_



Jackson County Planning Dept.

Dear Sirs,

Please accept this letter  
as my authorization to allow  
My Dwight Banner to apply  
for and receive well permits  
on any and all of my properties.

This letter will be zeped, so  
please accept even the zeped  
copies as my personal  
authorization.

Sincerely,  
C. S. H. 5

JACKSON COUNTY DEPARTMENT OF PLANNING & DEVELOPMENT

50 West Sixth Street  
Medford, Oregon 97501 - 776-7551

Owner Craig, Ash Twp. 34 Range 1W Section 20  
Tax Lot 2102 Code \_\_\_\_\_ Acreage \_\_\_\_\_  
Address/Directions to Property Reque River Dr. to Kitty Lane - Pky  
on N.W. corner as per plot plan.

(ALL FEES ARE NON-REFUNDABLE)

Site Evaluation Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ No. of Sites \_\_\_\_\_ Date: \_\_\_\_\_  
 Permit Application Fee 15500 Receipt # 1145 Date: 5-9-84  
New Installation \_\_\_\_\_ Repair/Alteration \_\_\_\_\_ Sewage Connection \_\_\_\_\_  
Well Permit Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ Date: \_\_\_\_\_

Proposed Use of Property SFR Test Holes Ready Yes  
Zoning Cleared Yes Number of Bedrooms 3

Comments: \_\_\_\_\_  
Bldg #84-417-M.

I certify that the information given is true and correct to the best of my knowledge.

Date: 5-9-84 Signature: [Signature]

Mailing Address (#, Street, City, State, Zip Code) 1225 Crater Lake Ave, Medford, Oregon 97504 Phone 772-1388

\*\*\*\*\* DO NOT WRITE BELOW THIS LINE \*\*\*\*\*

Site Evaluation: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By: \_\_\_\_\_ Date: \_\_\_\_\_  
WELL PERMIT: Approved \_\_\_\_\_ Not Approved \_\_\_\_\_ Date \_\_\_\_\_ By: \_\_\_\_\_  
Comments: \_\_\_\_\_ WELL PERMIT # \_\_\_\_\_

SEPTIC PERMIT INSTALLATION SPECIFICATIONS: 1000 Gallon Septic Tank (1250 gallon recommended)  
300 Square Feet of Drainfield: Install sand filter  
alternative septic system as specified in attached  
"Installation Narrative"

Keep drainfield and approved repair area free of all development, compaction, soil modification, traffic, heavy cultivation and fenced from livestock.

PERMIT: Approved  Not Approved \_\_\_\_\_ By: BWA/Rior R.S. # 15-13884N  
Date: 11 MAY 84 EXPIRES 11 MAY 85 Final Inspection On: \_\_\_\_\_  
Certificate of Satisfactory Completion Issued: \_\_\_\_\_ By: \_\_\_\_\_  
Installer: \_\_\_\_\_

SAND FILTER SEWAGE DISPOSAL SYSTEM

INSTALLATION NARRATIVE

Applicant: Gregg Adams

Permit # 15-138-84N

Twp. 34 Range 1W Section 20 Tax Lot 2102

**IMPORTANT NOTE:** If problems are anticipated during system layout or are encountered at any stage of installation, please call Jackson County Planning Department, Sanitation Division (776-7554) for assistance on how to proceed.

For persons unfamiliar with the installation of septic systems, installation handouts are available from the Jackson County Planning Department to help you.

If this system, or any part thereof, is installed by any person other than the property owner or a regular employee of the property owner, that person must be licensed to do such work by the state Department of Environmental Quality. Except that, the sand filter structure itself need not be constructed by a licensed septic system installer. Be sure to use approved materials in all construction. A list is available at this office.

I. GENERAL PERMIT CONDITIONS:

A) This alternative sewage disposal system is designed to service no more than one single family dwelling with a maximum of four (4) bedrooms. The maximum daily sewage flow must not exceed 450 gallons.

B) The drainfield portion of this system should be installed during dry weather conditions and when soil moisture content is relatively dry. Approval of soil moisture conditions by a Jackson County Department of Planning and Development sanitarian must be obtained before beginning drainfield excavation.

C) Issuance of this permit does not relieve the applicant of the responsibility of complying with all applicable local, state, and federal regulations regarding development of this property.

D) This installation permit is valid for one year from date of issue and is not transferable.

E) The owner of this sand filter system shall provide the Jackson County Department of Planning and Development written verification that the system's septic tank has been pumped at least once each forty-eight (48) months by a licensed sewage disposal service business. Service start date shall be assumed to be the date of issuance of the Certificate of Satisfactory Completion. The owner shall provide this office certification of tank pumping within two (2) months of the date required for pumping.

F) Before beginning construction, the installer of this system must contact a Jackson County Department of Planning and Development sanitarian or soil scientist to discuss installation details.

G) Unless otherwise noted herein, all provisions of Oregon Administrative Rules, Chapter 340, 71-100 through 73-085 and Appendices must be met.

H) The septic tank, dosing tank, sand filter, effluent sewer lines, and drainfield shall be installed in the locations indicated on the attached plot plan. Any change in the location of any of these components must be approved by this office prior to construction.

I) A Certificate of Satisfactory Completion, issued by the Jackson County Department of Planning and Development, is required before the system is used and will be issued only if all conditions of this permit are met.

II. SEPTIC TANK:

A) The liquid capacity of the septic tank shall be at least one thousand (1,000) gallons; a twelve hundred fifty (1,250) gallon septic tank is recommended. The tank must be placed level on a solid base (not fill).

B) The septic tank must be located outside of the approved "Usable Area". The minimum separation distance between the septic tank and the building foundation is five (5) feet. The septic tank should be installed as close to this minimum separation distance as possible in order to minimize opportunity for clogging of the building sewer.

C) If the septic tank is installed deeper than eighteen (18) inches under the surface, it must have a lidded eighteen (18) inch or greater diameter watertight riser located over the inlet tee and the access manhole. Risers must extend to the finish ground surface and be provided with weighted or securely fastened lids. The ground surface shall slope away from the top of each riser access lid to prevent water from entering the septic tank.

D) On sites where a high groundwater table is encountered, the septic tank and/or dosing tank must be weighted or provided with an antibuoyancy device to prevent flotation.

III. DOSING TANK SPECIFICATIONS:

A) The minimum liquid capacity of the dosing tank must be four hundred fifty (450) gallons. The liquid capacity of the tank is measured from the invert of the inlet to the tank bottom.

B) The dosing tank must have a liquid storage capacity of at least one hundred twenty-five (125) gallons between the alarm level and the inlet pipe invert.

C) The dosing tank must be provided with a lidded, watertight, eighteen (18) inch or greater diameter riser which extends to the finish ground surface. The ground surface must slope away from the top of the riser access lid to prevent water from entering the tank. The riser must be provided with a weighted or securely fastened lid.

D) The effluent sewer line between the septic tank and the dosing tank must be of approved three (3) or four (4) inch diameter sewer pipe only.

E) A two-compartment, 1,500 gallon "pumping" tank may be utilized to satisfy both the septic tank and dosing tank requirements of this permit.

F) On sites where a high groundwater table is encountered, the septic tank and/or dosing tank must be weighted or provided with an antibuoyancy device to prevent flotation.

G) The septic tank and dosing tank must be vented through the house plumbing system.

IV. PUMPS OR DOSING SIPHONS, CONTROLS, AND ALARMS:

A) A dosing siphon may be used instead of a pump to pressurize the sand filter system. We recommend checking with the siphon dealer as to proper installation procedures and minimum fall requirements. The dosing siphon must be a type approved for use in Oregon. The siphon must produce a vertical rise of three (3) to five (5) feet during the pressure test.

B) Pumps, controls, and alarms used in this system must comply with Oregon's electrical code and must be installed in accordance with the provisions of an electrical permit issued by the State Department of Commerce.

C) Installation of pumps, controls, and alarms shall also meet the provisions of Oregon Administrative Rules, Chapter 340, 73-055, AND the following minimum requirements:

Submersible pumps shall be provided with an easy, readily accessible means of electrical and plumbing disconnect and a noncorrosive lifting device as a means of removal for servicing.

A gate valve shall be provided inside the dosing tank between the quick disconnect and the exit of the tank if the sand filter is upslope of the dosing tank. A one-way check valve shall be provided between the pump and the quick disconnect fitting if the Sand Filter is located upslope of the dosing tank.

If the Sand Filter is located downslope of the dosing tank, a one-eighth (1/8) inch anti-siphon hole shall be located in the pressure line above the high water mark in the dosing tank.

Pumps must be capable of passing a three-quarter (3/4) inch solid sphere, and have a minimum one and one-quarter (1 1/4) inch discharge. Pumps must be placed a minimum of six (6) inches above the dosing tank bottom.

Pumps must be automatically controlled by sealed mercury switches with a minimum mercury tube rating of twelve (12) amps at one hundred fifteen (115) VAC. The mercury float switch pump controls shall be set to provide a pumping volume of ninety (90) gallons (12 cubic feet) per cycle. The pump must be placed within a corrosion-resistant screen that extends above the maximum effluent level within the pump chamber. The screen shall have at least twelve (12) square feet of surface area, with one-eighth (1/8) inch openings.

An audible, waterproof high level alarm with manual silence switch shall be located near the building served by the sand filter system. Alarm and pump controls must be on separate circuits. If the alarm is located inside a building, it must be an audio visual type with silence switch. The mercury float switch regulating the high water level alarm must be located at least five (5) inches above the "on" level.

The pump must be capable of producing five (5) feet of vertical head during the pressure test.

#### V. SAND FILTER PRESSURE PIPING:

A) All fittings and pressure piping between the dosing tank and the sand filter must be a minimum of class 160 PVC 1120 and have a minimum inside diameter of two (2) inches. Piping must be installed below the frost line, be bedded in three (3) inches of sand or pea gravel, and be uniformly supported along the trench bottom. Backfill must be free of large rock or material which will damage the piping.

B) The pressure piping within the sand filter itself must be at least 160 psi PVC pipe meeting ASTM D 2241. Joint cement compounds must conform to ASTM D 2564.

C) Pressure piping within the sand filter must be installed as shown in the enclosed diagram. Holes perforating the pressure distribution laterals must be one-eighth (1/8) inch diameter and spaced as shown in the enclosed diagram. Pressure distribution manifold piping must be two (2) inches in diameter; pressure distribution lateral piping must be two (2) inches in diameter and must be placed with drilled holes facing up.

VI. SAND FILTER SPECIFICATIONS:

A) The sand filter component of this system shall be constructed as specified in Building Permit #84-417-M issued by the Building Division of the Jackson County Department of Planning and Development. The construction of the sand filter must be inspected and approved (any concrete must be allowed to cure for at least fourteen (14) days) before any sand may be placed in the sand filter.

B) Perforated underdrain pipe and gravel cover, filter sand, filter fabric, filter rock, pressure piping, and approved soil crown shall be placed within the sand filter as shown in the enclosed diagram.

C) The perforated underdrain pipe must be standard, four (4) inch, smooth wall drainfield pipe. It shall be covered with gravel to a minimum depth of two (2) inches throughout the sand filter bottom to a total depth of six (6) inches. \*Filter fabric shall be placed over this gravel before placement of the filter sand.

D) Filter sand must conform to the specifications for "medium sand" contained in OAR 340 71-290 Sand Filter Rules. The filter sand must be thoroughly water-settled for 6 hours by sprinkling before the filter gravel is placed over the sand.

E) Filter gravel must be clean, washed crushed rock (1½ - 2½ inches in size) or clean, washed gravel (¾ to 2½ inches in size).

F) The filter gravel shall be covered with filter fabric.

G) Soil crown material shall be approved by the Jackson County Department of Planning and Development prior to placement. There shall be sufficient depth of soil to provide a six (6) inch crown (after settling), sloped to allow rainfall runoff.

VII. DRAINFIELD SPECIFICATIONS:

A) The drainfield portion of this septic system must be installed using a serial distribution design and be located only in the "Usable Area" designated on the site evaluation worksheet dated June 9, 1983. Reserve at least one-half of the "Usable Area" for future repair drainfield installation.

B) Install 150 lineal feet of twenty-four (24) inch wide disposal trench. Trench depth shall be held to 24-30 inches. Trenches must be installed uniformly level and spaced at ten (10) feet minimum on centers. It is very important to keep the trenches level end to end and not to exceed the maximum trench depth. Contouring the disposal trenches with the contour of the slopes may be necessary to maintain uniform depths. Trench sidewalls must be scarified before proceeding. Place six (6) inches of clean, washed crushed rock (1½" to 2½" in size) OR gravel (¾" to 2½" in diameter) in each trench, lay perforated distribution pipe (holes down) on level and centered in each trench, and cover pipe with at least two (2) inches of crushed rock or washed gravel. Pipe ends must be capped. Total depth of rock or gravel must be twelve (12) inches. Cover rock or gravel with one layer of untreated building paper or six inches of straw.

C) "Up-and-overs" from one trench to another consist of unperforated pipe placed on undisturbed earth. This will ensure full use of the trench sidewall and minimize settling of the overflow pipe. Do not dig a connecting trench and then recompact the excavated soil to obtain the desired rise. A six (6) inch rise is required for proper overflow. This is measured from the top of the disposal trench pipe to the top of the overflow pipe at its highest point. If a connection of two (2) pipes must occur in this "up-and-over", be sure the male end at the joint points downhill. Call for an inspection at this point.

24-36" OK 8/20/84 D.F.

D) The entire drainfield and any other areas disturbed as a result of construction must be liberally fertilized and seeded with high water use grasses such as alta fescue, orchard grass, and tall wheat-grass.

E) The site of the initial drainfield installation and the replacement area (repair area) must be kept vacant, free of all development, soil modification, compaction, traffic, heavy cultivation, fenced from all livestock, or any other activity which would damage the system.

VIII. SURFACE WATER DIVERSION DITCH SPECIFICATIONS:

A) Install a minimum twelve (12) inch wide, twelve (12) inch deep V-ditch a minimum of five (5) feet upslope of the upper drainfield line. The ditch must have a minimum fall of one-quarter ( $\frac{1}{4}$ ) inch per foot.

B) Outlet end(s) of the V-ditch must daylight at ground surface.

IX. INSPECTION SCHEDULE:

A) Inspections of the sand filter structure will be made by staff of the Building Division of the Jackson County Department of Planning and Development. All other inspections will be by Sanitation Division staff.

B) The Building Division will make inspections of the sand filter construction at the following points:

1) For reinforced concrete structures:

a) After forms for the sand filter have been erected, rebar is installed and pipes are roughed in, but before concrete is poured.

b) After concrete has been poured and forms are removed.

2) For vinyl-lined sand filters:

a) After the containment structure and/or excavation is completed and four (4) inch sand cushion is in place, but before vinyl-liner is installed.

C) The Sanitation Division shall be notified to make construction inspections at the following points:

1) After septic tank, dosing tank, sand filter, and disposal trenches have been staked out, but before construction begins.

2) After the drainfield trenches have been excavated, and the gravel, distribution pipe, and untreated building paper have been placed in the trenches, but before the trenches are backfilled.

3) After the septic tank, dosing tank, pressure transport piping, and effluent sewer line between the sand filter and the drainfield have been installed, but before they are backfilled.

4) After the sand filter underdrain pipe is placed and covered with gravel and filter fabric, the filter sand is placed and water-settled, six (6) inches of filter gravel is placed over the sand, the perforated pressure piping in the sand filter is installed, and installation of the pump, float switches and alarm is completed.

NOTE: Water and power must be available on the site during this inspection. This is to allow the electrical and mechanical systems to be evaluated under actual working conditions. The system must produce a vertical rise of water three (3) to five (5) feet high out of the one-eighth (1/8) holes in the pressure laterals.


5) After the remaining six (6) inches of filter gravel have been placed over the sand filter pressure piping and covered with filter fabric and the soil crown material has been placed on the sand filter.

This permit letter, the enclosed diagrams and permit placard constitute a permit for construction.

Inspections may be combined at the discretion of the Sanitation Division, Jackson County Department of Planning and Development.


Bradley W. H. Prior, R.S.  
Bradley W. H. Prior, R.S.  
Sanitarian Supervisor  
May 14, 1984

Plot Plan 344W-2-2102  
Gregg Adams Owner.



Kitty Lane.

Roque River Drive.





Department of Environmental Quality

RECEIVED

MAR 26 1984

JACKSON COUNTY  
PLANNING

522 S.W. FIFTH AVENUE, BOX 1760, PORTLAND, OREGON 97207 PHONE: (503) 229-5696

March 23, 1984

CERTIFIED MAIL

Mr. Gregg Adams  
1225 Crater Lake Ave.  
Medford, OR 97504

Re: WQ-SSS-Variance Denial  
T.L. 2102; Sec. 20;  
T. 23<sup>1</sup>/<sub>2</sub>S.; R. 1 W., W.M.;  
Jackson County

Dear Mr. Adams:

In response to your variance application, I visited your property on February 22, 1984, to gather soils and topographical information prior to conducting an information gathering hearing. The site was evaluated by Jackson County staff in 1983 and found suitable for placement of a capping fill initial system, with a conventional sand filter system designated for the future repair system. However, at a later date it was learned that the common property line between this property and the adjacent property to the north ran through the area approved for the capping fill. This eliminated use of the site unless and until an easement is secured that allows the system to be placed on the adjoining property. Test pits in the area of the system proposed for variance were observed to contain water at depths ranging from eight (8) to twelve (12) inches from the surface. The effective soil depth within the pits was found to vary from ten (10) to twenty (20) inches. In one area cemented very gravelly and cobbly sand was observed at the surface and perched groundwater was seeping out. The land surface slopes at six (6) to twelve (12) percent towards the east.

You have proposed to construct a capping fill initial system in the north-westernmost portion of the property. A sand filter system would be used for future replacement if needed. A curtain drain to intercept and divert groundwater would be located upslope from the capping fill system. The proposal would require variance from the following rules:

1. OAR 340-71-265(2)(b), which limits the use of capping fill systems to sites where the seasonally perched water levels do come within eighteen (18) inches of the ground surface at any time during the year or within six (6) inches of the disposal trench bottom. Observed water levels were at twelve (12) inches or less from the surface, and would be expected to come in contact with the disposal trench bottoms.
2. OAR 340-71-265(2)(e), which requires an effective soil depth of not less than eighteen (18) inches as measured from the natural soil surface. The effective soil depth in the pits was as shallow as ten (10) inches and as deep as twenty (20) inches, but was usually found at sixteen (16) inches or less. In one area between two (2) of the pits saprolite was observed at the ground surface.

Mr. Gregg Adams  
March 23, 1984  
Page 2


3. OAR 340-71-265(2)(g), which requires a minimum six (6) inch separation distance between the bottom of the disposal trench and the layer that limits effective soil depth. With trenches excavated twelve (12) inches deep (the minimum depth allowed), the separation distance would usually be four (4) inches or less.

Variance from particular requirements of the rules or standards pertaining to on-site sewage disposal systems may be granted if a finding can be made that strict compliance with the rule or standard is inappropriate for cause, or that special physical conditions render strict compliance unreasonable, burdensome, or impractical. The physical conditions at the site are adverse to the satisfactory operation of a capping fill alternative system. The shallow soil depths in combination with the seasonal rainfall, causes high fluctuating water levels to occur for several months each year. Where cemented very gravelly and cobbly sand is at the surface, the perched groundwater actually seeps out onto the surface. A curtain drain may intercept and divert some of the groundwater in the immediate area it is located, but its effectiveness will be reduced with distance. In my opinion a capping fill system receiving septic tank effluent will not function satisfactorily for an extended period of time. With high water levels (and shallow soil depths) effluent will pond in the trenches and cause the soil pores to become clogged with organic solids, insoluble metal sulfides, and bio-slimes. Being unable to pass through the trench sides and bottom, sewage effluent will seep out onto the ground surface. Based upon my review of the verbal and written testimony contained in the record, I am unable to make a favorable finding. Your variance is regretfully denied.

Pursuant to OAR 340-71-440, my decision to deny your variance request may be appealed to the Environmental Quality Commission. Requests for appeal must be made by letter, stating the grounds for appeal, and addressed to the Environmental Quality Commission, in care of Mr. Fred Hansen, Director, Department of Environmental Quality, Box 1760, Portland, Oregon 97207, within twenty (20) days of the date of the certified mailing of this letter.

Please feel free to contact me at 229-6443 if you have questions regarding this decision.

Sincerely,



Sherman O. Olson, Jr.  
Assistant Supervisor  
On-Site Sewage Systems Section  
Water Quality Division

S00:1  
XL3212

cc: ✓ Brad Prior, Jackson County  
Southwest Region Office, DEQ

ZONING CLEARANCE SHEET  
JACKSON COUNTY, OREGON

7/83

2/17

This clearance sheet is supplied for informational purposes. Land development regulations are subject to change. When a change does occur, it may invalidate this zoning clearance or otherwise alter conditions of approval.

PROPERTY LEGAL DESCRIPTION: Township 34, Range 1W, Section 20, Tax Lot 2102, Acres 3.72 <sup>lot 4</sup>  
ENTIRE T.L.

PROPERTY ADDRESS: Kitty Lane DATE TAX LOT CREATED: pre-zoning

OWNER OR APPLICANT: Daniel Lane TELEPHONE: \_\_\_\_\_ ADDRESS: \_\_\_\_\_

PROPOSAL:  First dwelling  Additional dwelling  Other - explain below\*

\* Septic Permit lot #3 has m/H on Property lot #4  
will have 1st Dwelling #83-116-LLA

This property is zoned RR-5 Minimum parcel size requirements \_\_\_\_\_

Development on this land is subject to Chapter 280.100 Mandatory Fire Safety Requirements of the Jackson County Land Development Ordinance.

A portion of this land is affected by:  A Floodplain.  An Airport Approach Overlay which could prohibit development as proposed.

MINIMUM STRUCTURAL SETBACK REQUIREMENTS FROM:

Front property line: 30' <sup>N.W.</sup> Side property line: 200' <sup>S.E.</sup> Rear property line: 20'

This property lies in a NONRESOURCE zoning district and abuts a RESOURCE zoning district. Special setbacks are required unless an exception is approved by staff.

BEFORE ZONING CLEARANCE CAN BE GIVEN FOR THE ABOVE PROPOSAL, THE OWNER/APPLICANT MUST APPLY FOR AND RECEIVE APPROVAL OF:

- Minor Partition  Major Partition  Subdivision
- Forest Site Plan Review  Farm/Nonfarm Dwelling  Conditional Use Permit
- Nonforest Site Plan Review  County Recognized Access  Temporary Mobile Home
- Commercial Site Plan Review  Administrative review for structures in a floodplain
- Variance  Administrative review for structures in an airport approach
- Alteration of nonconforming use  Other - see below

COMMENTS BY STAFF: Lot #3 has been given the Tax Lot #2125. Tax  
lot 2102 comprises lots 4 and 1 of Long Branch Subdivision  
As of this date no permits have been issued for lot #1 so this  
will be a first dwelling on 3.72 ac. Prior to permits being issued  
for lot #1 a new tax lot number must be assigned.

NO CONFLICTS EXIST. The proposed use or development as presented herein is in conformance with the Land Development Ordinance. Falsification of information renders this zoning clearance null and void.

CERTIFICATION: The statements and information herein contained and supplied by myself are, in all respects, true and accurate to the best of my knowledge and belief. I am aware that the above information supplied by Staff is subject to change from legislative or judicial acts of the county governing body, and realize the necessity to verify its accuracy should I refer to it at a later date.

Signature of owner/applicant: \_\_\_\_\_ Date: \_\_\_\_\_

Signature of Staff member: Dody Tolbert Date: 3-14-84

Copy of this zoning clearance  handgiven  mailed to applicant on: \_\_\_\_\_

INTEROFFICE MEMORANDUM - JACKSON COUNTY

---

TO: File: 35-1W-16-1100, 35-1W-1108, and 34-1W-20-2102

FROM: Ken Cote *K*

DATE: February 23, 1984

SUBJECT: Variance Hearing

I met on site on February 22, 1984, with Gregg Adams, Bob Pathe and Sherm Olson for a variance hearing. A capping fill system was proposed for these sites.

Ex. 6



# Department of Environmental Quality

522 S.W. FIFTH AVENUE, BOX 1760, PORTLAND, OREGON 97207 PHONE: (503) 229-5696

February 9, 1984

Mr. Gregg Adams  
1225 Crater Lake Avenue  
Medford, OR 97504

Re: WQ-SSS-Variance Assignment  
T.L. 2102; Sec. 20;  
T. 34 S.; R. 1 W., W.M.;  
Jackson County

Dear Mr. Adams:

The Department of Environmental Quality is in receipt of an application for variance from Oregon Administrative Rules governing on-site sewage disposal.

As discussed with you in a telephone conversation on February 8, 1984, I will meet at the proposed drainfield site on Wednesday, February 22, 1984, at approximately 11 a.m., to gather soils and topographical information relevant to your proposal. As specified on the variance application form, test pits must be dug to a depth of five (5) feet or to bedrock. Please refer to the attached plan of your proposal for the most desirable locations to place these test pits. Immediately after the site visit, an information gathering hearing, as provided for in OAR 340-71-430, will be held at the site. You are invited to have your attorney, consultant, and any other interested person in attendance at both the site visit and the information gathering hearing.

At the time of your hearing, please be prepared to offer the facts and reasons to allow a finding that strict compliance with the rule or standard is inappropriate for cause, or that special physical conditions render strict compliance unreasonable, burdensome, or impractical.

By receipt of a copy of this letter, Jackson County Department of Planning and Development is notified of this pending variance. It is requested that a representative be in attendance at both the site visit and the hearing.

If you have any questions, please feel free to contact me at 229-6443.

Sincerely,

Sherman O. Olson, Jr.  
On-Site Sewage Systems Section  
Water Quality Division

S00:g  
XG3206

Enclosure


cc: Brad Prior  
Southwest Region Office, DEQ

Kitty Drive

1" = 30 feet

Road - R.O.W.

Curb & Gutter



Remainder to be Serial Distribution

Recommended test Pit location

Capping fill Variance

T. 34, R. 1W, Sec 20

Tax Lot 2102

Sand Filter Repair System

RECEIVED

JAN 23 1984

Water Quality Dept. of Environment & Natural Resources

Application for Variance from Administrative Rules  
Regulating On-Site Sewage Disposal Systems

Ex. 1

83-15

rec # 28836  
C9 # 2673  
#225 of 450  
Balance to Richard  
W. Cox Variance  
1-20-84

complete this application form and submit the application fee\* (\$225) and required attachments to:  
Department of Environmental Quality, On-Site Sewage Systems Section, P.O. Box 1760, Portland, Oregon 97207

APPLICANT INFORMATION--Please Print

Gregg Adams  
Name of Owner  
1225 Crater Lake Ave.  
Address  
Medford Oregon 97504  
City State Zip Code  
772-1388 772-1388  
Business Phone Home Phone

34 1W 20  
Township Range Section  
2102 TAC  
Tax Lot or Account No. Parcel Size  
Subdivision Name Longbranch Subd.  
Lot 1 Block 1

ATTACHMENTS

RECEIVED  
JAN 23 1984

Provide The Following Items:

1. Complete and accurate directions to the property. A locator map would be helpful.
2. Two (2) copies of the parcel's legal description (metes and bounds, warranty deed, sales contract, or approved subdivision plat). Include the protective covenants, deed restrictions and easements, if applicable. Dept. of Environ. Quality
3. Two (2) copies of an assessor or title company plat map or a surveyor plat map.
4. Two (2) copies of a land use compatibility statement from the appropriate land use authority that your proposed land use is compatible with the LCDC acknowledged comprehensive plan or statewide planning goals.
5. Copies of all correspondence and field notes relating to past evaluations for septic tank-drainfield development on the subject property. A copy of the site evaluation report must be included.
6. Two (2) copies of narrative description of your variance proposal including the system construction specifications. Please list the step-by-step procedures that you propose to be followed for the installation of this system.
7. On a plot plan draw to a defined scale not smaller than one inch equals thirty feet, show the location and dimensions of the proposed drainfield and its replacement area. Indicate separation distances between disposal trenches, wells, springs, water courses, agricultural drainage tile, ditches, drainage ways, waterlines, buildings, roads, embankments, and other identifying features which help demonstrate parcel to drainfield relationships. Please provide two (2) copies.
8. Two (2) copies of a profile view of the proposal which illustrates the projected drainfield layout, trench dimensions, backfill depth, boundaries, (in cases where a crown over the drainfield is proposed), slope direction and percent of slope.

Hardship variances may be considered in cases of extreme and unusual hardship. The following factors may be considered: Advanced age or bad health of applicant; need of applicant to care for aged, incapacitated or disabled relative; and relative insignificance of the environmental impact of granting a variance. Documentation of hardship must be provided. FOR HARDSHIP CONSIDERATION MARK THIS BOX.

A minimum of two test pits must be provided within the specific area where the actual variance system is being proposed. The pits should be approximately two feet wide, four feet long, and excavated to either bedrock or to a depth of five (5) feet. Similar pits must be provided in the area of the repair system. The Variance Officer may require the proposed drainfield and the future replacement drainfield be staked out.

Please note that it is your responsibility to present all of the facts and the reasoning which you feel justifies the granting of the variance.

By my (our) signature(s), I (we) request the Department of Environmental Quality act on this application and hereby grant permission to enter onto the above described property.

Gregg Adams 12-1-83  
Signature of Owner Date

[Signature] 12-1-83  
Signature of Owner Date

NOTE: All owners must sign this application form. If there are more than two (2) owners, attach additional duplicate applications.

\* Pursuant to ORS 454,662, the applicant is not required to submit the application fee if, at the time of filing the application, the applicant is 65 years of age or older, is a resident of the State of Oregon, and has an annual household income, as defined in ORS 310.630, of \$15,000 or less. Appropriate documentation must be submitted with the application.

EX. 7

CAPPING FILL SYSTEM  
INSTALLATION NARRATIVE

Applicant: \_\_\_\_\_ Permit No. \_\_\_\_\_  
Twp. 34 Range 1W Section 20 Tax Lot 2102

I. GENERAL CONDITIONS:

A) This sewage disposal system is designed to serve no more than one single family dwelling with a maximum of three (3) bedrooms. Daily sewage flow will not exceed 450 gallons.

B) Construction of this system will occur between June 1 and October 1, unless otherwise authorized. The upper eighteen (18) inches of soil must not be saturated or moist enough to cause loss of soil structure and porosity when worked.

**RECEIVED**  
JAN 23 1984

II. SEPTIC TANK SPECIFICATIONS:

A) The liquid capacity of the septic tank will be at least one thousand (1,000) gallons; a twelve-hundred fifty (1,250) gallon septic tank is recommended. The tank will be placed level on a solid base (not fill). If the septic tank is located deeper than eighteen inches below the ground surface, an access riser to the ground surface will be required. On sites where a high groundwater table is encountered, the septic tank must be weighted or provided with an anti-buoyancy device to prevent flotation.

III. DRAINFIELD SPECIFICATIONS:

A) The drainfield portion of this septic system will be installed using a serial distribution design and be located only in the "Usable Area" designated on the attached site evaluation worksheet. At least one-half of the "Usable Area" will be for future repair drainfield installation.

B) \*IMPORTANT: Before beginning excavation of the disposal trenches, the initial drainfield installation site will be scarified (by rototilling or plowing) to break-up the surface layer of vegetation. The cap will not bond without this procedure.

C) Install 450 lineal feet of twenty-four (24) inch wide disposal trench will be installed. Trench depth will be held to twelve (12) inches. Trenches will be installed uniformly level and spaced at ten (10) feet minimum on centers. It is very important to keep the trenches level end to end and not to exceed the maximum trench depth. Contouring the disposal trenches with the contour of the slopes may be necessary to maintain uniform depths. Place six (6) inches of clean crushed rock or washed gravel (3/4" to 2 1/2" in diameter) in each trench, lay perforated distribution pipe (holes down) on level and centered in each trench, pipe ends must be capped. Cover pipe with at least two (2) inches of crushed rock or washed gravel. Total depth of rock or gravel must be twelve (12) inches. Cover rock or gravel with one layer of untreated building paper or six inches of straw. "Up and overs" from one trench to another consist of unperforated pipe placed on undisturbed earth. This will ensure full use of the trench sidewall and minimize settling of the overflow pipe. Do not dig a connecting trench and then recompact the excavated soil to obtain the desired rise. A six (6) inch rise is required for proper overflow. This is measured from the top of the disposal trench pipe to the top of the overflow pipe at its highest point. If a connection of two (2) pipes must occur in this "up and over", be sure the male end at the joint points downhill. Call for an inspection at this point.

IV. CURTAIN DRAIN SPECIFICATIONS:

A) Install a minimum twelve (12) inch wide, twenty-four (24) inch deep curtain drain a minimum of ten (10) feet upslope of the upper drainfield line. The trench must have a minimum fall of one-quarter (1/4) inch per foot fall.

B) Place visqueen on the trench bottom and along the downhill side of the excavated trench and extend to the ground surface.

C) Perforated pipe is centered in the trench bottom with the holes facing up. Place six (6) inches of drainfield rock over the pipe. Cover rock with untreated building paper or six (6) inches of straw, but do not backfill until inspected.

D) Outlet end(s) of the curtain drain must daylight at ground surface. Perforated end caps or noncorrosive screen must be securely placed on end(s) of pipe to prevent rodent nests from blocking drainage.

V. SOIL CAP SPECIFICATIONS:

A) The texture of the soil used for the cap shall be clay loam. Topsoil native to the property at a site removed from the drainfield installation area may be used as the capping material.


B) After the trench construction, site scarification, and fill material have been inspected and approved, apply twelve (12) inches to unsettled fill material over the site and work in (rototill) so that the native soil and fill are well mixed. The fill should be crowned in the middle and smoothed (not compacted) to prevent ponding. There shall be a minimum of ten (10) feet of separation between the edge of the fill and the nearest trench sidewall.

The site must be landscaped with grass and protected from livestock, automotive traffic, heavy cultivation or any other activity which would damage the system.


IV. The repair system will be a sand filter system as per DEQ specifications. The drainfield for the sand filter system will be located in area as shown on plot plan.

---

Gregg Adams  
Property Owner  
Date: January 17, 1984



TYPICAL Cross Section of  
Drainline.



RECEIVED

JAN 23 1964


Water Quality Division  
Dept. of Environmental Quality

Kitty Drive

1" = 306'

Road - R.O.W.

Curbside



Demingfield to be Serial Distribution

Capping Bill Variance  
 T. 34, R. 1W, Sec. 20  
 Tax Lot 2102  
 Sand Filter Repair System

**RECEIVED**  
 JAN 23 1964

Water Quality Division  
 Dept. of Environmental Quality

JACKSON COUNTY DEPARTMENT OF PLANNING & DEVELOPMENT  
WEST Sixth Street  
Medford, Oregon 97501 - 776-7551

site #7

Owner Ervin House Twp. 34 Range 1W Section 20  
Tax Lot 2102 Acreage 5  
Address/Directions to Property Rogue River Dr & Kitty

(ALL FEES ARE NON-REFUNDABLE)

Site Evaluation Fee 540<sup>00</sup> Receipt # 9877 No. of Sites 3 Date: 5-27-83  
 Permit Application Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ Date: \_\_\_\_\_  
 New Installation \_\_\_\_\_ Repair/Alteration \_\_\_\_\_ Sewage Connection \_\_\_\_\_  
 Well Permit Fee \_\_\_\_\_ Receipt # \_\_\_\_\_ Date: \_\_\_\_\_

Proposed Use of Property SFR Test Holes Ready 5-27-83  
Zoning Cleared \_\_\_\_\_ Number of Bedrooms 3 each.  
Comments: Lots 1, 2, 4 of Longbranch Subdivision

I certify that the information given is true and correct to the best of my knowledge.

Date: MAY 27, 1983 Signature: Ervin House  
1225 Crocker Lake Ave. Medford, Oregon 97504 Phone 772-1388  
Mailing Address (#, Street, City, State, Zip Code)


\*\*\*\*\* DO NOT WRITE BELOW THIS LINE \*\*\*\*\*

Site Evaluation:  
Based upon information provided us including a soils and topographic report made by Dick Florey on June 9 and June 22, 1983, we have found your drainfield sites to conform with minimum standards for the issuance of a permit to install a Sand Filter alternative sewage disposal system. An installation permit can be issued provided no conflicts exist with zoning requirements. This approved evaluation report shall remain in effect until issuance of a permit to construct unless in the meantime conditions on this or adjacent properties have been altered in any manner which would prohibit issuance of a permit, in which case, this evaluation report shall be considered null and void. Technical rule changes will not invalidate this report. This approval is for sites #2 and #4. Site #1 is approved for a Capping Fill initial system with a Sand Filter repair system. 7/14/83  
By: [Signature] Date: 8-11-83

WELL PERMIT: Approved \_\_\_\_\_ Not Approved \_\_\_\_\_ Date \_\_\_\_\_ By: \_\_\_\_\_  
Comments: \_\_\_\_\_ WELL PERMIT # \_\_\_\_\_

SEPTIC PERMIT INSTALLATION SPECIFICATIONS: \_\_\_\_\_ Gallon Septic Tank (1250 gallon recommended)  
\_\_\_\_\_ Square Feet of Drainfield: \_\_\_\_\_

Keep drainfield and approved repair area free of all development, compaction, soil modification, traffic, heavy cultivation and fenced from livestock.  
PERMIT: Approved \_\_\_\_\_ Not Approved \_\_\_\_\_ By: \_\_\_\_\_ # \_\_\_\_\_  
Date: \_\_\_\_\_ EXPIRES \_\_\_\_\_ Final Inspection On: \_\_\_\_\_  
Certificate of Satisfactory Completion Issued: \_\_\_\_\_ By: \_\_\_\_\_  
Installer: \_\_\_\_\_



Any Special Conditions for Permit:

Cap System Must be STAKED before Construction

Position	Relief	Scale
Ft. Slope Side Slope Top Fan	Smooth Concave Convex	1" = 40'

450 Gal/day. 150 lined / 150 gal, 12" trench depth, 18" Cap 12" Vditch

Depth	Texture	Structure	Poros	Mottling	Notes: (% Frags., Rooting, Depth, R or I, etc.)	Water Table
P 0-5	LT CL	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis	Faint		Depth
1						Type- P TP
1	5-16	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint	15-16" Ave to Sub	Slope %
1	16-32	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint	Cemented Sub	Up 9%
1					Cement is C&Ca?	Down 1%
P 0-4	LT CL	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis	Faint		Depth
1						Type- P TP
1	4-12	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint	70% P&K	Slope %
1	12-16	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		Up 9
1	16+	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		Down

Additional Notes: \* P/L MUST be Re-routed TO NORTH at least 10' from USEABLE AREA.

Most likely Pump will be Required.

SITE SUITABILITY: Cap fill, initial Sand FILTER Repair

USEABLE AREA: 75' x 50' ave. initial

Site Evaluation By: [Signature]

Date: 6/9/83 Second visit 6/22/83


Abbreviations

Lt. - light	C - clay	W - Weathered	Seds - Sedimentary
H - heavy	L - loam	Rx - Rocks	HW - Highly Weathered
F - fine	P - pebbles (2mm.-3")	Sub - Substrata	DG - Decomposing Granite
Co. - coarse	K - cobbles (3"-10")	Vol - Volcanic	RDM - Rapidly Draining material
S - sand(y)	St. - stones (+10")	Meta - Metamorphic	
Si. - silt(y)	V - very		

See new approval 7/30/84

Drawn 7/6/83

Copies: Yes X No



Red = Capping fill AREAS if Enough useable area - STAKING will be Required  
 Lot line adjustments or easements will be needed on  
 Some Lots S. FILES OK  
 SEE Individual Workbook Sheets for Dimensions

PLANNING CLEARANCE SHEET  
JACKSON COUNTY, OREGON

5/81

This clearance sheet is supplied for informational purposes and indicates a staff opinion or interpretation with regard to uses permitted within county zoning districts. Any disagreement with such opinion or interpretation is appealable through the process set forth in the zoning ordinance Chapter 285.020. Furthermore, zoning requirements are subject to change. When a change does occur it may invalidate the zoning clearance or alter conditions of the clearance.

PROPERTY LEGAL DESCRIPTION: Township 34, Range 16W, Section 20, Tax Lot 2102, Code \_\_\_\_\_

PROPERTY ADDRESS: ROGUE RIVER DR & KETTY DR ACREAGE: 5 DATE RECORDED: \_\_\_\_\_

APPLICANT: Erwin House, ADDRESS: \_\_\_\_\_

Proposed use:  First dwelling  Additional dwelling  Commercial (explain)

Other (explain) 4 S/E Lots 1, 2, 4 of Longbranch Subd.

See File 69-11-3 Longbranch Subdivision

This property is zoned: RP-5 Minimum parcel size and density requirements: \_\_\_\_\_

This zone permits your proposed use.  Your use requires a site plan review.

This zone requires a conditional use permit for your proposed use.

This zone does NOT provide for your proposed use. Alternate zone would be: \_\_\_\_\_

SETBACKS:  Minimum setbacks for structures not requiring site plan review are:

Front yard: 30' Side yard: 20' Rear yard: 20'

This property lies in a NONRESOURCE zoning district and abuts a RESOURCE zoning district. Special setbacks are required unless a variance is approved. See "comments" below.

Before clearance can be granted for the issuance of permits, evidence must be presented indicating compliance with the following:

New tax lot number must be assigned.  County recognized access requirements.

Major partition approval.  Minor partition approval.  Subdivision approval.

Parcel dimension requirement.  Parcel size requirement.  Setback requirements.

Site plan review requirements - special permit issued by Planning Department.

Variance requirements.  Floodplain regulations.

Conditional use permit approval.  Alteration of nonconforming use approval.

Comments by Staff: Lot number 4 abuts WR zoning. Therefore a buffer setback must be obtained from the northwest property line. In fire district and within 5 road miles of responding station.

NO CONFLICTS EXIST. The proposed use or development as presented herein is in conformance with the zoning ordinance. Falsification of information renders this zoning clearance null and void.


CERTIFICATION: The statements and information herein contained and supplied by myself are, in all respects, true and accurate to the best of my knowledge and belief. I am aware that the above information supplied by Staff is subject to change from legislative or judicial acts of the county governing body, and realize the necessity to verify its accuracy should I refer to it at a later date.

Signature of Applicant: Erwin House Date: May 27, 1983

Signature of Staff member: Dorothy Tubbs Date: 5-27-83

Copy of this zoning clearance  handgiven  mailed to applicant on: \_\_\_\_\_

White copy - Central File Pink copy - Applicant



Any Special Conditions for Permit:

Position	Relief	Undit.
Ft. Slope	HI Terrace	Smooth
Side Slope	Lo Terrace	Concave
Top	Btm	Convex
Fan	Other	Flmky

Depth	Texture	Structure	Pores	Mottling	Notes: (% Frags., Rooting, Depth, R or I, etc.)	Water Table Depth
P 0-12	Gr CL	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis	Faint	H: S	12
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
12-21	Comsted	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1	Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
P 0-7	Lr CL	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis	Faint		12
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
7-24	CL	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
24-34	Fx / Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint	Volcanic Substrata	
2		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
P 0-6	Similar	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis	Faint		12
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
6-20	Similar	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
20-44	to #2	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
P 0-20	CL 14's	Wk Mod St SG Bk Grn Ply Mas	Few Com Mny dis	Faint		12
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
20-35	Comsted	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1	Sub	Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		
1		Wk Mod St SG Bk Pri Ply Mas	Few Com Mny dis	Faint		

Additional Notes: #5 6-7% Down 0-16 to 18" CL  
16 to 18" - 30" CL & Sub (R) 16"

Many Little Colores in Sub

SITE SUITABILITY: Suitable for Paving  
USABLE AREA: 2 areas 50x70' & 125x65'  
Site Evaluation By: [Signature]

Date: 5/27/82  
Drawn 7/1/82

Abbreviations

- Lt. - light
- H - heavy
- F - fine
- Co. - coarse
- S - sand(y)
- Sl. - silt(y)
- C - clay
- L - loam
- P - pebbles (2mm.-3")
- K - cobbles (3"-10")
- St. - stones (+10")
- V - very

2/25

Owner Violet L. Farris Trwp. 34 Range 1W Section 20  
 Tax Lot 1-22323-4 Acreage 5

Address/Directions to property 1 1/2 miles (app) from Shady Cove on Rogue River Drive. Corner Kitty Dr & Rogue River Dr

PRELIMINARY SITE INSPECTION

COUNTER WORK  
 Soil Map Number, Series & Chances 1 1/2 55B Rich silt loam 2-7  
64D Carney clay 5-20

Comments 1st Dwelling

Fee: \$ 50<sup>00</sup> per site FEE: 50<sup>00</sup> #SITES 1 Receipt Number 9800 Date 2/25/82

Signature of Owner or authorized representative (in writing) Violet L Farris Mailing Address PO Box 183 Shady Cove Or. Telephone 878-2523  
~~878-2633~~

DO NOT WRITE BELOW THIS LINE


Ervin House

FIELD WORK  
 Appointment date & time 3/3/82 11 A.M.

Comments Met on site with MR. ERVIN HOUSE. The lot consists of a gentle foot slope high terrace position with shallow clay loam soils over cemented pan and/or volcanic rock. Chances for a standard system are very slim. The possibilities of a Capping-Fill system are good based on old soil work on this lot. For a Capping-Fill approval we need 18" minimum of good permeable soil before encountering anything restrictive such as clay, rock, or the cemented pan. The slope must be less than 12% and we need a suitable area of Time spent on site 20 minutes

Map of Recommended Area(s)

approximately 100' x 100'. As a last resort a sand filter would be a likely alternate. The "best area" for test pits is shown below. Mr. House wishes a drainfield down slope of this "best area" so I recommend pits where shown 80 to 100 feet apart. ☒ = Test Pits



Suggested digging test pits (Yes)  (No)  Number of possible sites 1  
 Standard  ETA  SAND FILTER   
 Capping Fill  Other   
 Field work by [Signature] Date March 3, 82

NOTE: IF YOU APPLY FOR A FORMAL SITE EVALUATION WITHIN 90 DAYS OF THE DATE OF THE PRELIMINARY SITE INSPECTION, THE NORMAL SITE EVALUATION FEE WILL BE REDUCED BY THE PRELIMINARY FEE. SITE EVALUATION APPLICATION MUST BE SUBMITTED BEFORE TEST HOLES WILL BE EVALUATED.

ANCE SHEET (subject to change)

JACKSON AREA,



PLANNING CLEARANCE SHEET  
JACKSON COUNTY, OREGON

2/25  
5/81

This clearance sheet is supplied for informational purposes and indicates a staff opinion or interpretation with regard to uses permitted within county zoning districts. Any disagreement with such opinion or interpretation is appealable through the process set forth in the zoning ordinance Chapter 285.020. Furthermore, zoning requirements are subject to change. When a change does occur it may invalidate the zoning clearance or alter conditions of the clearance.

PROPERTY LEGAL DESCRIPTION: Township 34, Range 1W, Section 20, Tax Lot 2102, Code \_\_\_\_\_

PROPERTY ADDRESS: KITTY DR & ROGUE RIVER DR ACREAGE: 5 DATE RECORDED: Pre existing

APPLICANT: VIOLET FARRIS, ADDRESS: Box 183, SHADY COVE, OR

Proposed use:  First dwelling  Additional dwelling  Commercial (explain)  
 Other (explain) PSI

\*\*\*\*\*  
This property is zoned: RR-5 Minimum parcel size and density requirements: 5 Acre

- This zone permits your proposed use.  Your use requires a site plan review.
- This zone requires a conditional use permit for your proposed use.
- This zone does NOT provide for your proposed use. Alternate zone would be: \_\_\_\_\_

SETBACKS: Minimum setbacks for structures not requiring site plan review are:  
Front yard: 30' Side yard: 20' Rear yard: 20'

This property lies in a NONRESOURCE zoning district and abuts a RESOURCE zoning district. Special setbacks are required unless a variance is approved. See "comments" below.

Before clearance can be granted for the issuance of permits, evidence must be presented indicating compliance with the following:

- New tax lot number must be assigned.  County recognized access requirements.
- Major partition approval.  Minor partition approval.  Subdivision approval.
- Parcel dimension requirement.  Parcel size requirement.  Setback requirements.
- Site plan review requirements - special permit issued by Planning Department.
- Variance requirements.  Floodplain regulations.
- Conditional use permit approval.  Alteration of nonconforming use approval.

Comments by Staff: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

NO CONFLICTS EXIST. The proposed use or development as presented herein is in conformance with the zoning ordinance. Falsification of information renders this zoning clearance null and void.  
\*\*\*\*\*

CERTIFICATION: The statements and information herein contained and supplied by myself are, in all respects, true and accurate to the best of my knowledge and belief. I am aware that the above information supplied by Staff is subject to change from legislative or judicial acts of the county governing body, and realize the necessity to verify its accuracy should I refer to it at a later date.

Signature of Applicant: \_\_\_\_\_ Date: \_\_\_\_\_  
Signature of Staff member: Robert S Olson Date: 2-25-82

Copy of this zoning clearance  handgiven  mailed to applicant on: \_\_\_\_\_

White copy - Central File      Pink copy - Applicant



Oregon Department of Environmental Quality  
Onsite Program

## Septic System DO's and DON'Ts

A properly constructed and maintained system can last a long time if you follow some common **Septic System DO's and DON'Ts**:

**DON'T** flush material that will not easily decompose, such as hair, diapers, cigarette butts, matches, or feminine hygiene products.

**DON'T** wash or flush medicines or hazardous chemicals like paint, paint thinner and bleach into the system. They kill the bacteria needed to decompose wastes in the septic tank and drain field.

**DON'T** drive over the septic tank or drainfield.

**Don't** flush flushable wipes. Many septic tank pumpers and city public works employees are finding they don't break down and cause serious headaches.

**DON'T** plant anything over or near the drain field except grass. Roots from nearby trees or shrubs may clog and damage drain lines.

**DON'T** dig in your drain field or build anything over it.

**DON'T** cover the drain field with a hard surface such as concrete or asphalt.

**DON'T** make or allow repairs to your septic system without obtaining the required permit. Use professionally licensed septic contractors when needed.

**DON'T** use septic tank additives. These products usually do not help and some may even be harmful to your system.

**DON'T** allow backwash from home water softeners or condensate from an air conditioner or heat pump to enter the septic system.

**DON'T** enter your tank. Any work to the tank should be done from outside. Gases that can be generated in the tank and/or oxygen depletion can be fatal.

**DO** conserve water to avoid overloading the system.

**DO** use substitutes for household hazardous waste.

**DO** learn the location of your septic tank and drain field. Keep a sketch of it handy with your maintenance records for service visits.

**DO** cover the drain field with a grass cover to prevent erosion and remove excess water.

**DO** keep your septic tank cover accessible for inspections and pumpings. Install risers if necessary.

**DO** keep a detailed record of repairs, pumpings, inspections, permits issued, and other maintenance activities.

**DO** divert other sources of water, like roof drains, house footing drains, and sump pumps, away from the septic system. Excessive water keeps the soil in the drain field from naturally cleansing the wastewater.

**DO** have your septic tank pumped out regularly by a DEQ licensed contractor.

**DO** call a professional whenever you experience problems with your system, or if there are any signs of system failure.

**Follow these septic system  
DO's and DON'TS !!!**

<b>DO'S</b>	<b>DON'TS</b>
<b>Conserve water</b>	<b>Overload system</b>
<b>Substitute for bleach and ammonia cleaners</b>	<b>Flush medicines and hazardous materials down drain</b>
<b>Plant grass on drainfield</b>	<b>Plant deep rooted plants near tank or drainfield</b>
<b>Know location of all system components</b>	<b>Park, drive on, or allow animals access to drainfield</b>
<b>Perform periodic septic system maintenance and inspections</b>	<b>Wait until there is a problem before inspecting your septic system</b>

**Don't Flush Household Hazardous Waste!**

Visit the HHW website for the drop-off location nearest to you!

<http://www.oregon.gov/deq/Hazards-and-Cleanup/hw/Pages/HHW-by-County.aspx>

Or call 1-800-732-9253

**Why You Care About Your  
Septic System**

**Protect Your Investment**

It is typically much cheaper to properly maintain a working septic system than it is to repair or replace a failing septic system.

**Protect Community Health**

Septic system owners, their neighbors, and the surrounding community run the risk of coming into contact with harmful bacterial and viral pathogens when septic systems are not properly maintained.

**Protect Drinking Water**

Septic systems that are not working properly can contaminate groundwater sources. More than 70% of all Oregonians are at least partially dependent on groundwater for their drinking water supplies!

**Protect Environment**

Septic systems that are not working properly can contaminate surface waters, which disrupts natural systems and impairs aquatic and riparian life.



Water Quality  
Onsite Program  
Eugene, OR 97401  
Phone: 541-686-7905  
[www.oregon.gov/deq](http://www.oregon.gov/deq)

**Be  
Septic  
Smart**



**What to consider BEFORE Buying a Home**



# Don't Take Chances...

## Know Before You Buy!

---

Septic systems are designed to collect and purify the water that goes down the drains in your home. There are two main parts to a conventional septic system.

---

### 1) Septic Tank

The septic tank is a watertight container buried in the ground. It is designed to collect all of the water that comes from your home. For example, every time you flush a toilet, or do a load of laundry, you are sending water to your septic tank. When water enters the septic tank, the solids sink to the bottom of the tank (sludge) and oils float to the top of the tank (scum). All of the liquid between the sludge and scum layers is called wastewater. Once the tank is full, wastewater is pushed from the septic tank to the drainfield.

### 2) Drainfield

The drainfield, also called leach field, usually consists of a series of trenches that sit below the ground. These trenches are filled with a porous material and covered with soil. Wastewater from the septic tank is dispersed into the trenches. Microbes then purify the wastewater, as it moves down through the soil profile below the trenches. Microbes are responsible for purifying your waste!

---

The microbes are doing *their* job, but what can *you* do to keep your system working properly? Follow these guidelines for Operation and Maintenance of your septic system.

---

### Operation:

The first step in keeping your septic system working is to make sure that you and your family are *using* it properly. Of course, *never* flush materials that are hard to decompose down your drains. For example, cigarette butts, hair and food scraps are not septic friendly! Check out a list of DO'S and DON'TS for septic systems on the back of this brochure!

### Maintenance:

Your septic system will need periodic maintenance even when you and a healthy microbial population are doing the job properly. Having periodic septic system inspections can help to save you thousands of dollars in expensive repairs or even system replacement!

Visit :

<http://www.oregon.gov/deq/Residential/Pages/Septic-Smart.aspx>

for a list of certified and experienced [Onsite Maintenance Providers](#).

**Have questions? Call 541-686-7905**

### Ask These Questions First !!!

#### **Is the system currently working?**

The best way to find out is to have a certified [Onsite Maintenance Provider](#) do an Existing System Evaluation.

#### **Are there maintenance, pumping or repair records?**

Checking maintenance records will help you to identify if potentially costly repairs may be needed.

#### **If the existing system fails, how will you repair it and what will it cost?**

Repairs or replacement can be expensive. Plan ahead for system expenses!

#### **Where is the existing system located?**

Planting, building or driving on the drainfield will ruin the system! There should also be a reserve area for a replacement system. Do not build or pave over the reserve area either!

#### **Is there a septic system permit on file with the DEQ or local County agency?**

If no permit is on file, the system may have been installed without a permit or be very old. You could be held responsible if the system fails or causes a public health risk.

#### **Will the existing system support any changes to the home?**

You may need a larger system if you make additions to the home. Ask *before* you build!

# Seller's Disclosures

**SELLER'S PROPERTY DISCLOSURE STATEMENT**

1 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524  
 2 10223231 (the "Property")

**INSTRUCTIONS TO THE SELLER**

- 3 Please complete the following form. Do not leave any spaces blank. Please refer to the line number(s) of the question(s) when you provide your
- 4 explanation(s). If you are not claiming an exclusion or refusing to provide the form under ORS 105.475(4), you should date and sign each page of
- 5 this disclosure statement and each attachment.
- 6 Each seller of residential property described in ORS 105.465 must deliver this form to each buyer who makes a written offer to purchase. Under ORS
- 7 105.475(4), refusal to provide this form gives the buyer the right to revoke their offer at any time prior to closing the transaction. Use only the section(s)
- 8 of the form that apply to the transaction for which the form is used. If you are claiming an exclusion under ORS 105.470, fill out only Section 1.
- 9 An exclusion may be claimed only if the seller qualifies for the exclusion under the law. If not excluded, the seller must disclose the condition of the
- 10 Property or the buyer may revoke their offer to purchase anytime prior to closing the transaction. Questions regarding the legal consequences of the
- 11 seller's choice should be directed to a qualified attorney.

**DO NOT FILL OUT THIS SECTION UNLESS YOU ARE CLAIMING AN EXCLUSION UNDER ORS 105.470**

12 **Section 1. EXCLUSION FROM ORS 105.462 TO 105.490:**  
 13 You may claim an exclusion under ORS 105.470 only if you qualify under the statute. If you are not claiming an exclusion, you must fill out Section 2  
 14 of this form completely.

15 *Initial only the exclusion you wish to claim.*

16 \_\_\_\_\_ This is the first sale of a dwelling never occupied. The dwelling is constructed or installed under building or installation permit(s) #  
 17 \_\_\_\_\_, issued by \_\_\_\_\_.

18 \_\_\_\_\_ This sale is by a financial institution that acquired the Property as custodian, agent or trustee, or by foreclosure or deed in lieu of foreclosure.

19 \_\_\_\_\_ Seller is a court appointed (*select only one*)  receiver,  personal representative,  trustee,  conservator, or  guardian.

20 \_\_\_\_\_ This sale or transfer is by a governmental agency.

21 Signature(s) of Seller(s) claiming exclusion:

22 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 23 Print \_\_\_\_\_  
 24 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 25 Print \_\_\_\_\_  
 26 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 27 Print \_\_\_\_\_  
 28 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 29 Print \_\_\_\_\_

30 Signature(s) of Buyer(s) to acknowledge Seller's claim:

31 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 32 Print \_\_\_\_\_  
 33 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 34 Print \_\_\_\_\_  
 35 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 36 Print \_\_\_\_\_  
 37 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 38 Print \_\_\_\_\_

**LINES WITH THIS SYMBOL ← REQUIRE A SIGNATURE AND DATE**

### SELLER'S PROPERTY DISCLOSURE STATEMENT

39 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524  
40 10223231 (the "Property")

**IF YOU DID NOT CLAIM AN EXCLUSION IN SECTION 1, YOU MUST FILL OUT THIS SECTION**

41 **Section 2. SELLER'S PROPERTY DISCLOSURE STATEMENT:**

42 (NOT A WARRANTY) (ORS 105.464)

43 NOTICE TO THE BUYER: THE FOLLOWING REPRESENTATIONS ARE MADE BY THE SELLER(S) CONCERNING THE CONDITION OF THE  
44 PROPERTY LOCATED AT 130 Kitty Dr, Eagle Point, OR 97524 (THE "PROPERTY").

45 DISCLOSURES CONTAINED IN THIS FORM ARE PROVIDED BY THE SELLER ON THE BASIS OF SELLER'S ACTUAL KNOWLEDGE OF THE  
46 PROPERTY AT THE TIME OF DISCLOSURE. BUYER HAS FIVE BUSINESS DAYS FROM THE SELLER'S DELIVERY OF THIS SELLER'S  
47 DISCLOSURE STATEMENT TO REVOKE BUYER'S OFFER BY DELIVERING BUYER'S SEPARATE SIGNED WRITTEN STATEMENT OF  
48 REVOCATION TO THE SELLER DISAPPROVING THE SELLER'S DISCLOSURE STATEMENT, UNLESS BUYER WAIVES THIS RIGHT AT OR  
49 PRIOR TO ENTERING INTO A SALE AGREEMENT.

50 FOR A MORE COMPREHENSIVE EXAMINATION OF THE SPECIFIC CONDITION OF THIS PROPERTY, BUYER IS ADVISED TO OBTAIN AND  
51 PAY FOR THE SERVICES OF A QUALIFIED SPECIALIST TO INSPECT THE PROPERTY ON BUYER'S BEHALF INCLUDING, FOR EXAMPLE,  
52 ONE OR MORE OF THE FOLLOWING: ARCHITECTS, ENGINEERS, PLUMBERS, ELECTRICIANS, ROOFERS, ENVIRONMENTAL  
53 INSPECTORS, BUILDING INSPECTORS, CERTIFIED HOME INSPECTORS, OR PEST AND DRY ROT INSPECTORS.

54 Seller (select one)  is  is not occupying the Property.

**I. SELLER'S REPRESENTATIONS**

55 The following are representations made by Seller and are not the representations of any financial institution that may have made or may make a loan  
56 pertaining to the Property, or that may have or take a security interest in the Property, or any real estate licensee engaged by Seller or Buyer.

57 (Select or fill in an answer to each question below. Select "N/A" if a question is not applicable to the Property.)

58 \*If you mark "Yes" on items with \*, attach a copy or explain on an attached sheet.

59 **1. TITLE**

- 60 A. Do you have legal authority to sell the Property? .....  Yes  No  Unknown
- 61 B. \*Is title to the Property subject to any of the following? .....  Yes\*  No  Unknown
- 62  First right of refusal  Option  Lease or rental agreement  Other listing  Life estate
- 63 C. \*Is the Property being transferred an unlawfully established unit of land? .....  Yes\*  No  Unknown
- 64 D. \*Are there any encroachments, boundary agreements, boundary disputes or
- 65 recent boundary changes? .....  Yes\*  No  Unknown
- 66 E. \*Are there any rights of way, easements, licenses, access limitations or claims
- 67 that may affect your interest in the Property? .....  Yes\*  No  Unknown
- 68 F. \*Are there any agreements for joint maintenance of an easement or right of way? .....  Yes\*  No  Unknown
- 69 G. \*Are there any governmental studies, designations, zoning overlays, surveys or
- 70 notices that would affect the Property? .....  Yes\*  No  Unknown
- 71 H. \*Are there any pending or existing governmental assessments against the Property? .....  Yes\*  No  Unknown
- 72 I. \*Are there any zoning violations or nonconforming uses? .....  Yes\*  No  Unknown

Buyer Initials \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Seller Initials RHP / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_



SELLER'S PROPERTY DISCLOSURE STATEMENT

73 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524
74 10223231 (the "Property")

- 75 J. \*Is there a boundary survey for the Property? ... [ ] Yes\* [X] No [ ] Unknown
76 K. \*Are there any covenants, conditions, restrictions or private assessments that affect
77 the Property? ... [ ] Yes\* [X] No [ ] Unknown
78 L. \*Is the Property subject to any special tax assessment or tax treatment that may
79 result in levy of additional taxes if the Property is sold? ... [ ] Yes\* [X] No [ ] Unknown

80 2. WATER

81 A. Household water

82 (1) The source of the water is (select ALL that apply): [ ] Public [ ] Community [X] Private [X] Other (specify) Well

83 (2) Water source information:

- 84 a. \*Does the water source require a water permit? ... [ ] Yes\* [X] No [ ] Unknown
85 If yes, do you have a permit? ... [ ] Yes [ ] No [ ] Unknown [ ] N/A
86 b. Is the water source located on the Property? ... [X] Yes [ ] No [ ] Unknown [ ] N/A
87 \*If not, are there any written agreements for a shared water source? ... [ ] Yes\* [ ] No [ ] Unknown [X] N/A
88 c. \*Is there an easement (recorded or unrecorded) for your access to or
89 maintenance of the water source? ... [ ] Yes\* [X] No [ ] Unknown
90 d. If the source of water is from a well or spring, have you had any of the
91 following in the past 12 months? ... [ ] Yes [X] No [ ] Unknown [ ] N/A
92 [ ] Flow test [ ] Bacteria test [ ] Chemical contents test
93 e. \*Are there any water source plumbing problems or needed repairs? ... [ ] Yes\* [X] No [ ] Unknown
94 (3) Are there any water treatment systems for the Property? UV light [X] Yes [ ] No [ ] Unknown
95 [ ] Leased [X] Owned

96 B. Irrigation

- 97 (1) Are there any [ ] water rights or [ ] other irrigation rights for the Property? ... [ ] Yes [X] No [ ] Unknown
98 (2) \*If any exist, has the irrigation water been used during the last five-year period? ... [ ] Yes\* [ ] No [ ] Unknown [X] N/A
99 (3) \*Is there a water rights certificate or other written evidence available? ... [ ] Yes\* [ ] No [ ] Unknown [X] N/A

100 C. Outdoor sprinkler system

- 101 (1) Is there an outdoor sprinkler system for the Property? ... [ ] Yes [X] No [ ] Unknown
102 (2) Has a back flow valve been installed? ... [ ] Yes [ ] No [ ] Unknown [X] N/A
103 (3) Is the outdoor sprinkler system operable? ... [ ] Yes [ ] No [ ] Unknown [X] N/A

104 3. SEWAGE SYSTEM

- 105 A. Is the Property connected to a public or community sewage system? ... [ ] Yes [X] No [ ] Unknown
106 B. Are there any new public or community sewage systems proposed for the Property? ... [ ] Yes [X] No [ ] Unknown
107 C. Is the Property connected to an on-site septic system? ... [X] Yes [ ] No [ ] Unknown
108 (1) If yes, when was the system installed? ... [X] Unknown [ ] N/A

Buyer Initials \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Seller Initials [Signature] / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

**SELLER'S PROPERTY DISCLOSURE STATEMENT**

109 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524  
 110 10223231 (the "Property")

- 111 (2) \*If yes, was the system installed by permit? .....  Yes\*  No  Unknown  N/A
- 112 (3) \*Has the system been repaired or altered? .....  Yes\*  No  Unknown  N/A
- 113 (4) \*Has the condition of the system been evaluated and a report issued? .....  Yes\*  No  Unknown  N/A
- 114 (5) Has the septic tank ever been pumped? .....  Yes  No  Unknown  N/A
- 115 If yes, when? .....  N/A
- 116 (6) Does the system have a pump? .....  Yes  No  Unknown  N/A
- 117 (7) Does the system have a treatment unit such as a sand filter or an aerobic unit? .....  Yes  No  Unknown  N/A
- 118 (8) \*Is a service contract for routine maintenance required for the system? .....  Yes\*  No  Unknown  N/A
- 119 (9) Are all components of the system located on the Property? .....  Yes  No  Unknown  N/A
- 120 D. \*Are there any sewage system problems or needed repairs? .....  Yes\*  No  Unknown
- 121 E. Does your sewage system require on-site pumping to another level? .....  Yes  No  Unknown

**4. DWELLING INSULATION**

- 122 A. Is there insulation in the:
- 123 (1) Ceiling? .....  Yes  No  Unknown
- 124 (2) Exterior walls? .....  Yes  No  Unknown
- 125 (3) Floors? .....  Yes  No  Unknown
- 126 B. Are there any defective insulated doors or windows? .....  Yes  No  Unknown

**5. DWELLING STRUCTURE**

- 129 A. \*Has the roof leaked? .....  Yes\*  No  Unknown
- 130 If yes, has it been repaired? .....  Yes  No  Unknown  N/A
- 131 B. Are there any additions, conversions or remodeling? agriculture building .....  Yes  No  Unknown
- 132 If yes, was a building permit required? .....  Yes  No  Unknown  N/A
- 133 If yes, was a building permit obtained? .....  Yes  No  Unknown  N/A
- 134 If yes, was final inspection obtained? .....  Yes  No  Unknown  N/A
- 135 C. Are there smoke alarms or detectors? .....  Yes  No  Unknown
- 136 D. Are there carbon monoxide alarms? .....  Yes  No  Unknown
- 137 E. Is there a woodstove or fireplace insert included in the sale? .....  Yes  No  Unknown
- 138 \*If yes, what is the make? Quadra - fire pellet stove model out-fitter-11
- 139 \*If yes, was it installed with a permit? .....  Yes\*  No  Unknown  N/A
- 140 \*If yes, is a certification label issued by the United States Environmental Protection
- 141 Agency (EPA) or the Department of Environmental Quality (DEQ) affixed to it? .....  Yes\*  No  Unknown  N/A
- 142 F. \*Has pest and dry rot, structural or "whole house" inspection been done within the
- 143 last three years? .....  Yes\*  No  Unknown

Buyer Initials \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Seller Initials dkp / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_



### SELLER'S PROPERTY DISCLOSURE STATEMENT

144 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524  
 145 10223231 (the "Property")

- 146 G. \*Are there any moisture problems, areas of water penetration, mildew odors or  
 147 other moisture conditions (especially in the basement)? Repaired - see attached  Yes\*  No  Unknown  
 148 \*If yes, explain on attached sheet the frequency and extent of problem and any insurance  
 149 claims, repairs or remediation done.
- 150 H. Is there a sump pump on the Property?  Yes  No  Unknown
- 151 I. Are there any materials used in the construction of the structure that are or have been  
 152 the subject of a recall, class action suit, settlement or litigation?  Yes  No  Unknown  
 153 If yes, what are the materials? \_\_\_\_\_
- 154 (1) Are there problems with the materials?  Yes  No  Unknown  N/A  
 155 (2) Are the materials covered by a warranty?  Yes  No  Unknown  N/A  
 156 (3) Have the materials been inspected?  Yes  No  Unknown  N/A  
 157 (4) Have there ever been claims filed for these materials by you or by previous owners?  Yes  No  Unknown  N/A  
 158 If yes, when? \_\_\_\_\_  N/A  
 159 (5) Was money received?  Yes  No  Unknown  N/A  
 160 (6) Were any of the materials repaired or replaced?  Yes  No  Unknown  N/A

#### 6. DWELLING SYSTEMS AND FIXTURES

- 162 If the following systems or fixtures are included in the purchase price, are they in good working order on the date this form is signed?
- 163 A. Electrical system, including wiring, switches, outlets and service  Yes  No  Unknown
- 164 B. Plumbing system, including pipes, faucets, fixtures and toilets  Yes  No  Unknown
- 165 C. Water heater tank  Yes  No  Unknown
- 166 D. Garbage disposal  Yes  No  Unknown  N/A
- 167 E. Built-in range and oven  Yes  No  Unknown  N/A
- 168 F. Built-in dishwasher  Yes  No  Unknown  N/A
- 169 G. Sump pump  Yes  No  Unknown  N/A
- 170 H. Heating and cooling systems
- 171 (1) Heating systems  Yes  No  Unknown  N/A  
 172 (2) Cooling systems  Yes  No  Unknown  N/A
- 173 I. Security system  Owned  Leased  Yes  No  Unknown  N/A
- 174 J. Are there any materials or products used in the systems and fixtures that are or have  
 175 been the subject of a recall, class action suit settlement or litigation?  Yes  No  Unknown  
 176 If yes, what product? \_\_\_\_\_
- 177 (1) Are there problems with the product?  Yes  No  Unknown  N/A  
 178 (2) Is the product covered by a warranty?  Yes  No  Unknown  N/A  
 179 (3) Has the product been inspected?  Yes  No  Unknown  N/A

Buyer Initials \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Seller Initials AKP / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

G. We have had two water-related incidents:

1) In June 2023 the floor in front of the kitchen sink was damp. We hired a contractor who said the metal clamp holding the water line had loosened allowing water to seep out from under the sink and floor nearby. It impacted a few square feet. Repairs were made and American Modern Insurance paid the \$3,065.70 claim. There have been no further problems.

2) In March 2025 an area of the floor in the guest bath felt soft underfoot. We hired a contractor who repaired the water line feeding into that room and repaired all damage in this room. American Modern Insurance paid the claim for \$9,343.31. There have been no further problems.

New  
insulation  
in guest  
bath

March  
2025





SELLER'S PROPERTY DISCLOSURE STATEMENT

180 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524
181 10223231 (the "Property")

182 (4) Have claims been filed for this product by you or by previous owners? ... Yes No Unknown N/A
183 If yes, when? \_\_\_\_\_

184 (5) Was money received? ... Yes No Unknown N/A

185 (6) Were any of the materials or products repaired or replaced? ... Yes No Unknown N/A

186 7. COMMON INTEREST

187 A. Is there a Home Owners' Association or other governing entity? ... Yes No Unknown
188 Name of Association or Other Governing Entity: \_\_\_\_\_
189 Contact Person: \_\_\_\_\_
190 Address: \_\_\_\_\_
191 Phone Number: \_\_\_\_\_

192 B. Regular periodic assessments: \$ \_\_\_\_\_ per Month Year Other \_\_\_\_\_

193 C. \*Are there any pending or proposed special assessments? ... Yes\* No Unknown

194 D. Are there shared "common areas" or joint maintenance agreements for facilities
195 like walls, fences, pools, tennis courts, walkways or other areas co-owned in
196 undivided interest with others? ... Yes No Unknown

197 E. Is the Home Owners' Association or other governing entity a party to pending
198 litigation or subject to an unsatisfied judgment? ... Yes No Unknown N/A

199 F. Is the Property in violation of recorded covenants, conditions and restrictions or in
200 violation of other bylaws or governing rules, whether recorded or not? ... Yes No Unknown N/A

201 8. SEISMIC

202 A. Was the house constructed before 1974? ... Yes No Unknown
203 If yes, has the house been bolted to its foundation? ... Yes No Unknown N/A

204 9. GENERAL

205 A. Are there problems with settling, soil, standing water or drainage on the Property
206 or in the immediate area? ... Yes No Unknown

207 B. Does the Property contain fill? ... Yes No Unknown

208 C. Is there any material damage to the Property or any of the structure(s) from fire,
209 wind, floods, beach movements, earthquake, expansive soils or landslides? ... Yes No Unknown

210 D. Is the Property in a designated floodplain? ... Yes No Unknown
211 Note: Flood insurance may be required for homes in a floodplain.

212 E. Is the Property in a designated slide or other geologic hazard zone? ... Yes No Unknown

213 F. \*Has any portion of the Property been tested or treated for asbestos, formaldehyde,
214 radon gas, lead-based paint, mold, fuel or chemical storage tanks or contaminated
215 soil or water? ... Yes\* No Unknown

216 G. Are there any tanks or underground storage tanks, (for example, septic, chemical, fuel,
217 etc.) on the Property? ... Yes No Unknown
Septic

Buyer Initials \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Seller Initials [Signature] / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_



### SELLER'S PROPERTY DISCLOSURE STATEMENT

218 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524  
219 10223231 (the "Property")

220 H. Has the Property ever been used as an illegal drug manufacturing or distribution site? .....  Yes  No  Unknown  
221 \*If yes, was a Certificate of Fitness issued? .....  Yes\*  No  Unknown  N/A

222 **10. FULL DISCLOSURE BY SELLER(S)**

223 A. \*Are there any other material defects affecting this Property or its value that a  
224 prospective buyer should know about?.....  Yes\*  No  
225 \*If yes, describe the defect on attached sheet and explain the frequency and extent  
226 of the problem and any insurance claims, repairs or remediation.

### VERIFICATION

227 The foregoing answers and attached explanations (if any) are complete and correct to the best of my/our knowledge and I/we have received a copy  
228 of this disclosure statement. I/we authorize my/our agents to deliver a copy of this disclosure statement to all prospective buyers of the Property or  
229 their agents.

230 Total number of pages attached, including all addenda, reports, or any other documents. (complete even if zero) 2

231 Seller Linda K Perdue Date/Time May 19, 2026 ← 1:35 pm  
232 Print Linda K Perdue

233 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
234 Print \_\_\_\_\_

235 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
236 Print \_\_\_\_\_

237 Seller \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
238 Print \_\_\_\_\_

### II. BUYER'S ACKNOWLEDGMENT

239 A. As buyer(s), I/we acknowledge the duty to pay diligent attention to any material defects that are known to me/us or can be known by me/us by  
240 utilizing diligent attention and observation.

241 B. Each Buyer acknowledges and understands that the disclosures set forth in this statement and in any amendments to this statement are made  
242 only by Seller and are not representations of any financial institution that may have made or may make a loan pertaining to the Property, or that  
243 may have or take a security interest in the Property, or of any real estate licensee engaged by Seller or Buyer. A financial institution or real estate  
244 licensee is not bound by and has no liability with respect to any representation, misrepresentation, omission, error or inaccuracy contained in  
245 another party's disclosure statement required by this section or any amendment to the disclosure statement.

246 C. Buyer (which term includes all persons signing the "buyer's acknowledgment" portion of this disclosure statement below) hereby acknowledges  
247 receipt of a copy of this disclosure statement (including attachments, if any) bearing Seller's signature(s).

248 DISCLOSURES, IF ANY, CONTAINED IN THIS FORM ARE PROVIDED BY THE SELLER ON THE BASIS OF SELLER'S ACTUAL KNOWLEDGE  
249 OF THE PROPERTY AT THE TIME OF DISCLOSURE. IF THE SELLER HAS FILLED OUT SECTION 2 OF THIS FORM, YOU, THE BUYER, HAVE  
250 FIVE BUSINESS DAYS FROM THE SELLER'S DELIVERY OF THIS DISCLOSURE STATEMENT TO REVOKE YOUR OFFER BY DELIVERING  
251 YOUR SEPARATE SIGNED WRITTEN STATEMENT OF REVOCATION TO THE SELLER DISAPPROVING THE SELLER'S DISCLOSURE UNLESS  
252 YOU WAIVE THIS RIGHT AT OR PRIOR TO ENTERING INTO A SALE AGREEMENT.

Buyer Initials \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_



### SELLER'S PROPERTY DISCLOSURE STATEMENT

253 Property Address or Tax ID # 130 Kitty Dr, Eagle Point, OR 97524  
 254 10223231 (the "Property")

255 BUYER HEREBY ACKNOWLEDGES RECEIPT OF A COPY OF THIS SELLER'S PROPERTY DISCLOSURE STATEMENT.

256 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 257 Print \_\_\_\_\_

258 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 259 Print \_\_\_\_\_

260 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 261 Print \_\_\_\_\_

262 Buyer \_\_\_\_\_ Date/Time \_\_\_\_\_ ←  
 263 Print \_\_\_\_\_

264 Agent receiving disclosure statement on Buyer's behalf to sign and date:

265 Real Estate Agent \_\_\_\_\_ ← Real Estate Firm (identify) \_\_\_\_\_  
 266 Date received by Agent \_\_\_\_\_

Seller Initials JKP / \_\_\_\_ / \_\_\_\_ / \_\_\_\_

# Home Inspection



# ROGUE INSPECTION SERVICES

5415077674

[fastreply@rogueinspection.com](mailto:fastreply@rogueinspection.com)

<http://www.rogueinspection.com>



## INSPECTION REPORT

130 Kitty Dr  
Eagle Point, OR 97524

Jim & Linda Perdue

06/04/2026



Inspector

**Travis Hand**

OCHI #2150

5415077674

[travis@rogueinspection.com](mailto:travis@rogueinspection.com)



Agent

**Ashley Lacer**

(541) 231-7788

[ashley@martinoutdoorproperties.com](mailto:ashley@martinoutdoorproperties.com)

---

# TABLE OF CONTENTS

1: INSPECTION DETAILS	6
2: GROUNDS	7
3: EXTERIOR	8
4: ROOF	10
5: STRUCTURE	12
6: FIREPLACES	14
7: HVAC	15
8: ELECTRICAL	18
9: PLUMBING	19
10: INTERIOR	22
11: APPLIANCES	24
12: PESTS	26
13: ADDITIONAL INFORMATION	27

**THIS REPORT IS INTENDED ONLY FOR THE USE OF THE PERSON PURCHASING THE HOME INSPECTION SERVICES. NO OTHER PERSON, INCLUDING A PURCHASER OF THE INSPECTED PROPERTY WHO DID NOT PURCHASE THE HOME INSPECTION SERVICES, MAY RELY UPON ANY REPRESENTATION MADE IN THE REPORT.**

## **INTRODUCTION, SCOPE, DEFINITIONS & COMPLIANCE STATEMENT**

### **Introduction:**

The following numbered and attached pages are your home inspection report. The report includes pictures, information, and recommendations. This inspection was performed in accordance with the current Oregon Standards of Practice for Home Inspectors. The Standards contain certain and very important limitations, expectations and exclusions to the inspection. A copy is available upon request.

### **Scope:**

A home inspection is intended to assist in evaluating the overall condition of the dwelling. The inspection is based on observation of the visible, readily accessible and apparent condition of the structure and its components on this day. The results of this inspection are not intended to make any representation regarding the presence or absence of concealed defects that are not reasonably ascertainable or readily accessible in a competently performed inspection. No warranty, guarantee or insurance by Rogue Inspection Services, LLC is expressed or implied. This report does not include inspection for mold, lead or asbestos. A representative sampling of the building components is viewed in areas that are accessible at the time of the inspection. No destructive testing or dismantling of components is performed. Not all defects will be identified during this inspection. Unexpected repairs should be anticipated. The person conducting your inspection is not a Structural Engineer or other professional whose license authorizes the rendering of an opinion as to the structural integrity of a building or its other component parts. You are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. Rogue Inspection Services, LLC recommends that the professional making any repairs inspect the property further, in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing, including Qualified HVAC, Plumbing, Electrical, Engineering and Roofing Contractors.

### **Use of photos:**

Your report includes many photographs which help to clarify where the inspector went, what was looked at, and the condition of a system or component at the time of the inspection. Some of the pictures may be of deficiencies or problem areas, these are to help you better understand what is documented in this report and may allow you see

areas or items that you normally would not see. A pictured issue does not necessarily mean that the issue was limited to that area only, but may be a representation of a condition that is in multiple places. Not all areas of deficiencies or conditions will be supported with photos.

**Comment Key or Definitions:**

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

**What really matters in a home inspection:**

The process can be stressful. A home inspection is supposed to give you reassurance but often has the opposite effect. You will be asked to absorb a lot of information in a short time. This often includes a written report, checklist, photographs, environmental reports and what the inspector himself says during the inspection. All this combined with the seller's disclosure and what you notice yourself makes the experience even more overwhelming. What should you do? Relax. Most of your inspection will be maintenance recommendations, life expectancies and minor imperfections. These are nice to know about. However, the issues that really matter will fall into four categories: 1. Major defects. An example of this would be a significant structural failure. 2. Things that may lead to major defects. A small water leak coming from a piece of roof flashing, for example. 3. Things that may hinder your ability to finance, legally occupy or insure the home. Structural damaged caused by termite infestation, for example. 4. Safety hazards. Such as a lack of AFCI/GFCI outlet protection. Anything in these categories should be corrected. Often a serious problem can be corrected inexpensively to protect both life and property (especially in categories 2 and 4). Most sellers are honest and are often surprised to learn of defects uncovered during an inspection. Realize that sellers are under no obligation to repair everything mentioned in the report. No home is perfect.



MINOR



MODERATE



SIGNIFICANT

- ⊖ 2.7.1 GROUNDS - Grading & Drainage : Downspouts - Draining Near Foundation
- 🔧 3.1.1 EXTERIOR - Wood & Engineered Siding: Siding - Gap / Hole
- 🔧 3.3.1 EXTERIOR - Eaves, Soffits & Fascias: Eaves - Gaps / Holes
- 🔧 4.1.1 ROOF - Asphalt Shingles: Shingles - Debris
- 🔧 4.1.2 ROOF - Asphalt Shingles: Shingle - Granule Loss (Minor)
- 🔧 4.3.1 ROOF - Roof Drainage Systems: Gutter - Debris
- 🔧 5.2.1 STRUCTURE - Crawlspace: Access Cover - Gaps
- 🔧 7.1.1 HVAC - Forced Air Furnaces: Furnace - End Of Life Expectancy
- 🔧 7.2.1 HVAC - Air Conditioning: Air Conditioner - End Of Estimated Life Expectancy
- ⊖ 7.2.2 HVAC - Air Conditioning: Coolant - R-22
- 🔧 9.1.1 PLUMBING - Hose Bibs: Hose Bib - Not Secure
- ⊖ 9.2.1 PLUMBING - Water Heaters: Catch Pan - Not Present
- 🔧 9.2.2 PLUMBING - Water Heaters: End Of Life - Expectancy
- ⚠️ 9.4.1 PLUMBING - Distribution Lines: Water Lines - Polybutylene
- ⊖ 9.8.1 PLUMBING - Sinks & Components: Sink Drain - No Trap
- ⊖ 10.8.1 INTERIOR - Smoke & CO Detectors: C/O Alarm - Not Present
- 🔧 11.2.1 APPLIANCES - Ranges: Range - Anti-Tip Bracket Missing
- ⊖ 11.6.1 APPLIANCES - Laundry Connections: Laundry - Discharge Leak
- ⊖ 12.2.1 PESTS - Rodents, Bats & Birds: Rodent - Entry Point

# 1: INSPECTION DETAILS

## Information

---

### INSPECTION OVERVIEW

The following is an overview of general inspection details of the property. Any photos that maybe below, were taken at time of inspection for your reference.

**Inspection Type**

Pre-Listing

**Building Type**

Manufactured

**Structure Faces**

South

**Orientation**

Cover Photo

**Occupancy**

Occupied, Furnished

**Attendance**

Inspector, Seller

**Utilities**

All Utilities On

**Weather**

Clear

**Temperature**

80-90 F

**Structures Inspected**

Home

**Photos Are Representative**

Photos are only a representative sample of conditions observed. There may be more than one area of concern not shown by photo

## Limitations

---

### General Information

**OCCUPIED HOME**

Homes that are occupied at the time of inspection may have conditions that change from the time of inspection to the time of the closing. It would be wise for the prospective home owner to perform a walk through inspection after the home has been vacated to determine if there are any conditions that may have changed.

## 2: GROUNDS

### Information

#### GROUNDS OVERVIEW

The grounds of a property encompass the exterior land surrounding a home, which plays a critical role in property maintenance, drainage, and overall aesthetic appeal. This area includes landscaping, vegetation, soil conditions, grading, and various exterior features that contribute to the property's functionality and visual character. Understanding the grounds helps homeowners manage potential issues related to water management, plant health, soil stability, and environmental interactions with the home's structural elements.

#### Lot Type

Slight Slope

#### Soil Conditions

Dry

#### Driveway Material

Gravel

#### Walkway Material

Concrete

#### Patio Material

Concrete

#### Fence Material

Woven Wire

#### Deck Material

Wood

#### Retaining Walls

N/A

#### Sprinkler System

None Observed

#### Hot Tub

No

#### Pool

No

### Deficiencies

#### 2.7.1 Grading & Drainage

#### DOWNSPOUTS - DRAINING NEAR FOUNDATION

 Moderate

The downspout(s) around the structure drain too close to the foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement and damage to siding. Recommend adding extensions or splash blocks where needed to properly channel water away from home.

[Here is a helpful DIY link](#) and video on draining water flow away from your foundation.

Recommendation

Contact a handyman or DIY project



# 3: EXTERIOR

## Information

### EXTERIOR OVERVIEW

The following information pertains to the exterior of the structure. We inspected all exterior doors and the exterior portions of the windows. We looked for moisture damage/intrusion and inspected for defects and improper installation of siding, trim and roof overhangs in accessible areas from the ground.

#### Siding

Engineered Wood

#### Soffits

Closed

#### Windows

Vinyl, Thermal

#### Exterior Doors

Metal

#### Window Information

Any deficiencies in the windows in this section primary refer to the exterior portions only. For more details about the windows, see the interior section of this report.

## Limitations

Exterior Information

### EXTERIOR LIMITATIONS

We inspect the exterior of the structure that is visible and accessible only. We are unable to view inside of walls or behind items covering or blocking access. We only inspect the exterior visible from the ground. We probe areas susceptible to rot and moisture damage and do not probe the entire exterior looking for moisture damage as that would be technically exhaustive.

## Deficiencies

3.1.1 Wood & Engineered Siding

### SIDING - GAP / HOLE

There were gaps/holes present on the exterior siding. Recommend sealing to prevent moisture damage and/or insect/rodent access.

Recommendation

Contact a handyman or DIY project



Water Heater Door

### 3.3.1 Eaves, Soffits & Fascias

#### **EAVES - GAPS / HOLES**

There were gaps/holes observed at the eaves. This can allow rodents and/or insects to access the attic space at this location. Recommend that a qualified person repair/seal as necessary.

Recommendation

Contact a qualified professional.



Right Of Home

## 4: ROOF

### Information

#### ROOF OVERVIEW

The following information pertains to the roof. We inspected the roof coverings, drainage system, flashings, penetrations through the roof, and looked for signs of leaks in the roof system unless otherwise noted in the limitations area of this report. Any photos below are general photos for your reference.

<b>Inspection Method</b>	<b>Roof Style</b>	<b>Pitch</b>
Fully Traversed	Gable	3:12
<b>Roofing Material</b>	<b>Gutter Material</b>	<b>Flashing Material</b>
Asphalt Shingle	Metal	Metal
<b>Skylights</b>	<b>Ventilation Type</b>	<b>Chimney Exterior</b>
None	Pan vents, Soffit Vents	Metal Flue Pipe

#### Life Expectancy

As prescribed in the inspection authorization and agreement, this is a visual inspection only. Roofing life expectancy can vary depending on several factors. Any estimates of remaining life are approximations only.

#### Life Expectancy 8-10 Years

The roof was in good condition at the time of inspection. estimate 8-10 years of remaining life on the roof.

### Limitations

Roof Information

#### ROOF LIMITATIONS

Roofs are designed to shed water like an umbrella and are not waterproof. In events of wind driven rains, and periods of intense rain, water can sometimes blow into areas such as ridge vents, roof vents and valleys and present leaking conditions. This occurrence is rare, but can possibly happen in severe storm events. Unless it is raining at the time of inspection, some roof leaks may not be identified during the inspection process.

### Deficiencies

#### 4.1.1 Asphalt Shingles

##### SHINGLES - DEBRIS



There is debris and foliage on the roof. Recommend cleaning and monitoring a couple times a year to keep the rooftop and downspouts clean and clear of debris. The debris can cause prolonged moisture contact and accelerate the deterioration of the roof and is more likely to cause leaks.

Recommendation

Recommended DIY Project



#### 4.1.2 Asphalt Shingles

### SHINGLE - GRANULE LOSS (MINOR)



There was minor granule loss observed at the roof shingles. This is a normal process as the roof ages. Recommend monitoring for significant granular loss.

Recommendation

Recommend monitoring.



#### 4.3.1 Roof Drainage Systems

### GUTTER - DEBRIS



There were debris in the gutter(s) at time of inspection. Recommend cleaning to facilitate water flow.

[Here is a DIY resource](#) for cleaning your gutters.

Recommendation

Contact a handyman or DIY project



## 5: STRUCTURE

### Information

---

#### STRUCTURE OVERVIEW

We inspected the visible and accessible portions of the structure. Many portions of the structure were not visible due to being covered with finish materials, insulation, below grade etc. We looked for damaged or improper construction of structural components as well as looked for signs of moisture intrusion and pests.

<b>Foundation Type</b> Crawlspace	<b>Foundation Material</b> Masonry Block	<b>Foundation Tie Downs</b> Not Visible
<b>Floor Structure</b> Steel I-Beams, 2x6	<b>Floor Support</b> Masonry Block	<b>Sub-floor</b> Particle Board
<b>Wall Structure</b> Wood, Concealed	<b>Ceiling Structure</b> Not Visible	<b>Roof Structure</b> Not Visible
<b>Roof Sheathing</b> Not Visible		

#### CRAWLSPACE OVERVIEW

The following information pertains to the homes crawlspace and its accessible and visible components. Below are some general views of the crawlspace at time of inspection.

<b>Crawlspace Entry</b> Exterior - Right of Home	<b>Crawlspace Observation</b> Crawled	<b>Percent of Crawlspace Traveled</b> 100%
<b>Crawlspace Ventilation</b> Vented	<b>Crawlspace Floor</b> Vapor Retarder	<b>Insulation</b> Loose Fill, Fiberglass Batts

### Limitations

---

Structure Information

#### STRUCTURE LIMITATIONS

We only inspected areas of the structure there were visible and accessible at time of the inspection. Much of the structure is hidden behind wall coverings, siding, sheathing insulation, below grade etc. We can only report on items that are visible and accessible, unknown conditions may exist.

Crawlspace Information

#### CRAWLSPACE LIMITATIONS

We inspect accessible and safe areas of the crawlspace only. Many items and components are concealed by insulation and insulation/vapor barriers. We do not remove insulation or barriers etc. We cannot determine if a crawlspace will encounter moisture or pest issues, we can only report on what was observed at time of inspection. Crawlspace should be checked annually at a minimum to look for moisture, structural and pest issues etc.

## Attic

**NO ACCESS - MANUFACTURED HOME**

There was no attic access found on the home. This is normal for a manufactured home but limits our inspection of the roof structure, insulation etc.

---

## Wall Structure

**NOT VISIBLE**

The wall structure was not inspected due to being concealed behind wall coverings, siding, insulation etc., unknown conditions may exist.

---

## Floor Structure

**MANUFACTURED HOME - INSULATION BARRIER**

There was an insulation barrier (belly wrap) installed on the underside of the manufactured home. This is normal for a manufactured home as this is what holds the insulation in place and protects the underside of the home. However, this limits our inspection of the structural components, plumbing system, electrical wiring etc. Unknown and hidden conditions may exist such as, plumbing leaks, moisture related damage and pest issues etc.

---

## Roof Structure

**NOT VISIBLE**

The roof structure was not able to be inspected, due to lack of access to the attic, or no attic access.

**Deficiencies**

---

## 5.2.1 Crawlspace

**ACCESS COVER - GAPS**

The crawlspace access cover had gaps/openings observed. Recommend it be properly sealed by a qualified person to help prevent pest and rodents from entering crawlspace.

## Recommendation

Contact a qualified handyman.



## 6: FIREPLACES

### Information

---

#### FIREPLACE OVERVIEW

The following information pertains to the homes fireplace(s) and their visible and accessible components. Below are some photos of the fireplace/stove for reference:

<b>Type</b> Pellet burning	<b>Certified</b> Yes	<b>Cleanout</b> Bottom Tray
<b>Controls</b> Thermostat	<b>Chimney Liner</b> Metal Flue	<b>Level of Cleanliness</b> Good

#### Pellet Stove Operational

The pellet stove was in good working condition at the time of inspection.

#### Fireplace Fan

Yes

### Limitations

---

Fireplace Information

#### FIREPLACE/STOVE LIMITATIONS

Inspection of fireplaces and stoves is limited to the accessible and visible components only. Inspecting of the interior flue is beyond the scope of a typical home inspection. We recommend that all flues be cleaned by a qualified chimney sweep before use and on a regular basis.

# 7: HVAC

## Information

---

### HEATING SYSTEM OVERVIEW

The following information pertains to the heating system and its visual and accessible components. Below are some photos of the heating equipment for reference, thermal image(s) are of the supply air temperature at register(s) at the time of this inspection.

<b>Brand</b> Coleman	<b>Location</b> Hallway	<b>Energy Source</b> Electric
<b>Filter Location</b> Forced Air Unit	<b>Filter Type</b> Washable	<b>Heat Type</b> Heat Pump
<b>Ductwork</b> Insulated, Rigid	<b>Thermostat</b> Digital	<b>Manufacture Date</b> 2001 Approximate

### Air Conditioning System

Yes

### Typical Life Expectancy

- Gas Furnace 15-25 years
- Electric Furnace 15-25 years
- Heat Pump 10-20 years
- Boilers 20-35 years
- Mini Split 8-15 years
- Baseboard / Wall Heaters 12-18 years
- Electric Radiant Heat (heated floor) 25-40 years

Many factors including preventive maintenance, consistency of use, and load demand can play a large factor in the life expectancy of a heating system. Towards the end of a units life, expect to have increased energy usage and maintenance cost.

### System Service

Ask the property owner when it was last serviced. If unable to determine the last service date, or if this system was serviced more than 1 year ago, recommend that a qualified HVAC contractor service this system and make repairs if necessary. Any needed repairs noted in this report should be brought to the attention of the contractor when it's serviced.

### Furnace Operational

Heat system appears to be in working order. Supply air from the heating system should be 100 degrees Fahrenheit or higher.

### COOLING OVERVIEW

The following information pertains to the air conditioning system and its visible and accessible components. Any photos below are for your reference.

<b>Brand</b> Payne	<b>Location</b> Exterior - Left of Home	<b>Energy Source</b> Electric
<b>Configuration</b>	<b>Thermostat</b>	<b>Manufacture Date</b>

Central

Shared with Heating

2001 Manufacture Year

## Life Expectancy

- Stand Alone 12-15 years
- Heat Pump 10-20 years
- Mini Split 8-15 years

Many factors including preventive maintenance, consistency of use, and load demand can play a large factor in the life expectancy of a cooling system. Towards the end of a units life, expect to have increased energy usage and maintenance cost.

## System Service

It is recommended to have cooling equipment serviced annually by a qualified HVAC professional for increased service life.

## Appears Functional

The temperature split differential between the return air and supply registers was within the 14-22 degree (F) range at time of inspection.

## Limitations

Heating System Information

### HVAC LIMITATIONS

Many HVAC components and systems are beyond the scope of a typical home inspection, such as but not limited to: Wood fired heat systems, electronic air filters, solar systems, humidifiers/dehumidifiers, timers etc. We only inspect systems that are readily accessible and visually examine and test for function using normal operating controls.

Heating System Information

### DATA PLATE - NOT FOUND

We were unable to find a data plate on the heating equipment at time of inspection. We were unable to gather information such as, when the unit was manufactured.

## Deficiencies

7.1.1 Forced Air Furnaces

### FURNACE - END OF LIFE EXPECTANCY



The furnace/air handler was at or beyond its service life expectancy according to industry experts. HVAC equipment that is 15-20 years of age or more is at a higher risk to fail and replacement parts may not be available for repairs. Recommend service or inquiring with seller regarding service records during due diligence period. Recommend budgeting for a replacement system.

Recommendation

Recommend monitoring.



## 7.2.1 Air Conditioning

**AIR CONDITIONER - END OF ESTIMATED LIFE EXPECTANCY**

The cooling system was at or beyond its service life expectancy according to industry experts. HVAC equipment that is 10-15 years of age or more is at a higher risk to fail and replacement parts may not be available for repairs. Recommend budgeting for a replacement system.

## Recommendation

Recommend monitoring.



## 7.2.2 Air Conditioning

**COOLANT - R-22**

The HVAC system uses R-22 coolant. R22 leaks are highly toxic and can damage the environment and people's health. The use of R22 freon in air conditioning units has been restricted & banned from being used in any new products. If the unit is leaking or fails in the near future, it will need to be replaced. Recommend evaluation by an HVAC professional.

## Recommendation

Contact a qualified professional.



# 8: ELECTRICAL

## Information

---

### ELECTRICAL OVERVIEW

The following information pertains to the electrical system. We inspected the accessible and visible portions of the electrical system. We inspected the service entrance conductors, service equipment, grounding, over-current devices and distribution panels. We inspected the branch circuit conductors and their compatibility of their amperage, voltages and material type. We tested all accessible exterior outlets and a representative number of interior outlets for polarity and function. We tested the lighting by operating the switches and tested all ground/arc fault devices, smoke alarms and carbon monoxide detectors that were present and accessible. Any limitations to this inspection will be noted in the limitations section of this report. The following photos are for your reference.

<b>Service Type</b> Overhead	<b>Service Size</b> 240 Volts	<b>Service Conductors</b> Aluminum
<b>Main Panel Location</b> Utility Pole	<b>Panel Type</b> Circuit Breakers	<b>Panel Capacity</b> 200 AMP
<b>Panel Manufacturer</b> Crouse-Hinds	<b>Wiring Method</b> Romex	<b>Branch Wiring</b> Copper

### Sub Panel

Garage, Shop, Master Bedroom

### Low Voltage Systems

Any low voltage systems were not inspected and are excluded from this inspection. Including but not limited to: phone/telecom systems, cable coaxial systems, internet wiring, alarm systems, low voltage lighting and applicable wiring, etc.

### GFCI Protection

Ground Fault Circuit Interrupter (GFCI) is a protection feature that allows a circuit or receptacle to "trip" or "shut off" if as little as a 5 milliamp differential is detected between the "hot" and "neutral" conductors. This protection is recommended for receptacles within 6 feet of a sinks edge, or where something plugged into a receptacle could come into contact with water, including: bathrooms, kitchens, on the exterior, in garages, laundry rooms, and basements and crawl spaces. Although GFCI protection may not have been required in some or all of these areas when the home was built, their installation is highly recommended and is typically inexpensive. This protection, if present, was tested and was in satisfactory condition at the time of inspection, unless otherwise noted in this report.

More information on GFCI protection and the years certain areas where required to be protected can be viewed here: <https://prohitn.com/gfci-protection/>

## Limitations

---

Electrical Information

### ELECTRICAL LIMITATIONS

Only visible and accessible components of the electrical system are evaluated. Wiring behind walls, floors, ceilings, insulation etc. are not visible and therefore not inspected. Outlets, switches and other electrical components that are not accessible are not evaluated.

# 9: PLUMBING

## Information

---

### PLUMBING OVERVIEW

The following information pertains to the plumbing system. We inspected the visible and accessible portions of the plumbing system. We inspected the water supply and distribution system including piping materials and looked for leaks. We ran water at all accessible faucets including; sinks, tubs, showers and hose bibs attached to the home and observed the functional flow. We ran water down all accessible sink, shower and tub drains and observed the functional drainage and checked for leaks. Any photos below are for your reference.

<b>Water Source</b> Well	<b>Water Shut-Off</b> Pump House	<b>Water Supply Material</b> PVC
<b>Distribution Material</b> Pex, Polybutylene	<b>Drain Size</b> 2", 3"	<b>Drain Material</b> ABS
<b>Water Treatment</b> Sediment Filter, Pressure Tank	<b>Clean-out Location</b> Crawlspace	<b>Sump Pump</b> None Found
<b>Gas Service</b> Propane	<b>Gas Shut-Off</b> At Tank	

### Water Pressure Information

We do not test the water pressure as it is beyond the scope of a standard home inspection. For your information, water pressure between 50 to 80 PSI is acceptable, but 60 to 75 PSI is ideal. Water pressure that is too high may cause damage to fixtures and fittings.

### Jetted Tub - Operational

The jetted tub was in good operational condition at time of inspection. Recommend the jets be cleaned on a regular basis to prevent soap scum and periodically checking the plumbing underneath for leaks.

### WATER HEATER OVERVIEW

The following information pertains to the water heating system. We inspected the water heating equipment, temperature and pressure relief valve, strapping, electrical components, valves, flues, piping, checked for leaks and checked the water temperature. Any photos below are for your reference.

<b>Location</b> Exterior Closet	<b>Energy Source</b> Electric	<b>Type</b> Tank
<b>Capacity</b> 50 Gallon	<b>Drain Pan</b> None	<b>Seismic Straps</b> Yes
<b>Manufacturer</b> Bradford White	<b>Manufacture Date</b> 2009 Year	

### Life Expectancy & Maintenance

Water heaters have a typical life expectancy of 8 to 12 years. I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

[Here is a nice maintenance guide from Lowe's to help.](#)

## Operational

The water heater was in good working condition at the time of inspection.

## Limitations

Plumbing Information

### PLUMBING LIMITATIONS

Only visible and accessible components of the plumbing system are evaluated. Pipes behind walls, floors, ceilings, insulation etc. are not visible and therefore not inspected. Valves are not turned on if off at time of inspection as we do not know the reason why.

Water Heater Information

### WATER HEATER LIMITATIONS

The inspection of water heating systems is limited to the visible and accessible components only. We are not able to evaluate the interior of water heater tanks or interior components etc.

## Deficiencies

9.1.1 Hose Bibs

### HOSE BIB - NOT SECURE



The hose bib(s) were loose/unsecured at time of inspection. Water supply pipes can be stressed when hose bibs are turned on and off and when hoses are pulled, leaks and damage may occur as a result. Recommend that a qualified professional properly secure hose bib(s) as necessary.

Recommendation

Contact a qualified professional.



Right Of Home

9.2.1 Water Heaters

### CATCH PAN - NOT PRESENT



There was no catch pan installed underneath the water heater(s). Catch pans help prevent moisture related issues/damaged from a potential water heater leak. Recommend a qualified professional install a catch pan with proper discharge.

Recommendation

Contact a qualified professional.




## 9.2.2 Water Heaters

**END OF LIFE - EXPECTANCY**

The water heater(s) were at the end of their estimated life expectancy (10-12 years). While the unit(s) may last longer in good operating condition, we really recommend monitoring and budgeting to replace in the near future.

Recommendation

Recommend monitoring.



## 9.4.1 Distribution Lines

**WATER LINES - POLYBUTYLENE**

Water supply piping that appeared to be polybutylene was observed. Polybutylene piping was commonly installed in homes between the late 1970s and mid-1990s and has a documented history of premature failure. Over time, the material and fittings can become brittle and may leak or rupture without visible warning, which can result in water damage. Because of its known performance concerns, many insurers and buyers view this material as a higher risk. It is recommended that a qualified plumbing contractor further evaluate the system and consider replacement with more modern, widely accepted piping materials to reduce the potential for future leakage.

Recommendation

Contact a qualified plumbing contractor.



## 9.8.1 Sinks &amp; Components

**SINK DRAIN - NO TRAP**

There were no trap(s) observed at the sink drain(s). A lack of a trap can allow sewer gases to enter the home. Recommend proper trap(s) be installed by a plumbing contractor to help prevent sewer gases from entering the home.

Recommendation

Contact a qualified plumbing contractor.



Master Bathroom

# 10: INTERIOR

## Information

---

### INTERIOR OVERVIEW

The following information pertains to the interior. We inspected the interior and looked for major defects and safety issues. We inspected accessible and visible portions of floors, walls, ceilings, cabinets, counters, stairs/railings and a representative number of windows and interior doors. We looked for signs of abnormal or harmful water penetration in the structure. Issues that are considered as cosmetic are not addressed in this report. (Holes, stains, scratches, unevenness, missing trim, paint and finish flaws or odors). It is not the intent of this report to make the property new again.

#### Wall Material

Drywall

#### Ceiling Material

Paneling

#### Floor Coverings

Carpet, Laminate, Vinyl, Tile

#### Interior Doors

Hollow Core, Raised Panel

#### Window Type

Thermal, Sliders

#### Cabinetry

Wood

#### Countertops

Laminate

#### Bath Exhaust Fans

Yes

#### Smoke Detectors

Yes, Bedrooms, Living Room

#### Carbon Monoxide Alarms

None Found

#### Thermal Scan

No

### Smoke Detector Information

The smoke detector should be tested at common hallway to bedrooms upon moving in to home. For many years NFPA 72, National Fire Alarm and Signaling Code, has required as a minimum that smoke alarms be installed inside every sleep room (even for existing homes) in addition to requiring them outside each sleeping area and on every level of the home.

Recommend testing all smoke and CO2 detectors upon moving into the home. According to the U.S. Fire Administration (USFA), smoke detectors should be tested at least once a month and batteries should be replaced at least once or twice a year.

### Carbon Monoxide Alarm Information

In order to **maximize the protection of your home** from excess levels of carbon monoxide, place your detectors in all of the following places:

- On every level of your home. In order to ensure that your home has maximum protection, its important to have a CO detector on every floor.
- Five feet from the ground. Carbon monoxide detectors can get the best reading of your homes air when they are placed five feet from the ground.
- Near every sleeping area. If your CO levels get too high during the nighttime, its important that detectors can be heard by everyone sleeping in your home. Place your detectors close enough to every sleeping area so that they can awaken everyone in the case of an emergency.
- Near attached garages. Cars produce carbon monoxide any time they are running. If you have an attached garage, those gasses can quickly spread to the rest of your house. A CO detector near your attached garage will warn you if that becomes a problem.
- Where the manufacturer recommends. Every model of carbon monoxide detector is tested according to manufacturer specifications. Its important to take those specifications into account when youre deciding where to place your detectors.

## Deficiencies

---

## 10.8.1 Smoke &amp; CO Detectors

**C/O ALARM - NOT PRESENT**

There was no carbon monoxide alarm(s) observed in required areas during the inspection. Homes with a combustion source such as but not limited to: wood/gas/pellet stove/fireplace, gas cooktop, gas furnace, gas water heater, etc. and any home with an attached garage regardless of a combustion appliance or wood burning stove/fireplace must have carbon monoxide alarms installed in appropriate locations. Recommend installing carbon monoxide alarm(s) in accordance with OAR 837-047-0110

**OAR 837-047-0110**

*Install CO alarms on each level of your home with bedrooms (sleeping areas).*

*A CO alarm must be located within each bedroom or within 15 feet outside of each bedroom door. Bedrooms on separate floors in a structure containing two or more stories require separate CO alarms.*

## Recommendation

Contact a qualified handyman.

# 11: APPLIANCES

## Information

### APPLIANCE OVERVIEW

The following information pertains to the built-in appliances. Unless otherwise noted in the limitations or deficiencies area below, all appliances tested were in working order at time of inspection. Any photos below are for your reference.

<b>Cooking Equipment Type</b> Range	<b>Cooking Energy Source</b> Electric	<b>Anti-Tip Bracket</b> No
<b>Cooking Vent Type</b> Vented	<b>Built-in Microwave</b> No	<b>Dishwasher</b> Yes
<b>Garbage Disposal</b> Yes	<b>Trash Compactor</b> No	<b>Hot Water Dispenser</b> No
<b>Refrigerator</b> Yes, Freestanding	<b>Refrigerator Water Connection</b> Yes	<b>Washer Hookups</b> Yes
<b>Dryer Vent</b> Metal Pipe, Metal Flex	<b>Dryer Energy Source</b> 220 Volts	

### Laundry Connections: Washer & Dryer - Not Inspected

The washing machine and dryer are not inspected and fall outside of the scope of our home inspection. These units are not built in appliances. For the scope of this inspection we evaluate the connections necessary for these appliances to work. Any issues with the washer and dryer are not covered by this inspection.

## Deficiencies

### 11.2.1 Ranges


#### RANGE - ANTI-TIP BRACKET MISSING



There did not appear to be an anti-tip bracket installed at the range. The range could tip forward, especially if a child were to stand/sit on the door while it was open. Recommend a qualified person install a proper anti-tip bracket for safety.

Recommendation

Contact a qualified handyman.



## 11.6.1 Laundry Connections

**LAUNDRY - DISCHARGE LEAK** Moderate

There appears to be a leak at the washer discharge. Monitor and repair as needed.

Recommendation

Contact a qualified professional.



# 12: PESTS

## Information

### PEST OVERVIEW

Your peace of mind matters to us. Even though Oregon's Standards of Practice don't require it, we go beyond the basics by looking for visible signs of termites, rodents, and other pests that could affect your home's structure. If we see anything of concern during your inspection, we'll clearly note it here so you have the information you need to protect your investment.

### Wood Destroying Organisms (WDO):

A visual inspection was performed for termites and other wood-destroying organisms. No visible evidence of activity or damage was observed at the time of inspection. This was a limited, non-invasive inspection; hidden or future activity may exist. Ongoing annual inspections by a licensed pest control professional are recommended.

## Deficiencies

### 12.2.1 Rodents, Bats & Birds

 Moderate

#### RODENT - ENTRY POINT

There were possible rodent entry point(s) observed. Recommend a qualified professional properly seal any potential entry points to help prevent pest intrusion.

#### Recommendation

Contact a qualified professional.



Back Of Home Under Deck

# 13: ADDITIONAL INFORMATION

## Information

---

### Recommended Professionals

For a list of trusted professionals that we recommend. [Click Here](#)

### Questions or Concerns

Please remember we are your client for life! If you have any questions about your inspection or report, please don't hesitate to contact us and we will be more than happy to help. 541-507-7674

### The Final Walk-Through

The walkthrough serves as a final check for any remaining, unresolved issues with the home. Follow this checklist to ensure you don't overlook any steps.

- Turn on and off every light fixture.
- Run water and check for leaks under sinks.
- Test all appliances
- Check garage door openers.
- Open and close all doors.
- Flush toilets.
- Inspect ceilings, wall, and floors.
- Run the garbage disposal and exhaust fans.
- Test the heating and air conditioning.
- Open and close windows.
- Make sure all debris is removed from the home.
- Ensure all requested appliances and furnace are present.

### Exterior Photos

The following photos are general views of the exterior, taken at time of inspection for your reference.





### Roof Photos

The following photos are general views of the roof, taken at time of inspection for your reference.



### Interior Photos

The following photos are general views of the interior, taken at time of inspection for your reference.





### Fireplace Photos

The following photos are general views of the fireplace, taken at the time of inspection for your reference.




### HVAC Photos

The following photos are general views of the HVAC system/components, taking at time of inspection for your reference.




### Electrical Photos

The following photos are general views of some of the electrical systems/components, taking at time of inspection for your reference.




### Plumbing Photos

The following photos are general views of some of the plumbing systems/components, taking at time of inspection for your reference.



### Appliance Photos

The following photos are general views of the appliances, taken at time of inspection for your reference.



### Crawlspace Photos

The following photos are general views of the crawlspace, taken at time of inspection for your reference.



### Garage Photos

The following are photos taken of the garage at time of inspection that maybe useful for your reference.



### Outbuilding Photos

The following are photos taken of the outbuilding at time of inspection that maybe useful for your reference.

